



User manual

SURFACE ANALYST™

3001/5001



TABLE OF CONTENTS

Table of contents	2		
1. Introduction	3	5.3	Take a Measurement 16
1.1 Copyright	3	5.4	View the Measurement Results 18
1.2 Symbols used in the manual	3	5.5	Accepting or Rejecting the Drop Detection 19
1.3 Symbols on the product	3	5.6	Viewing Drop History 19
		5.6.1	The Drop History Screen 19
		5.6.2	Chart Results 20
2. Overview of the Surface Analyst	4	5.7	Adding a Drop Note 20
2.1 Specifications	4	5.8	Uploading Data Via USB 21
2.2 Surface energy and contact angles	5	5.9	Changing Your Password 24
2.3 How the Surface Analyst Works	5	5.10	Viewing the Software License, Settings, and Other Information 25
		5.11	Viewing Installed Options 25
3. Safety	6	5.12	Turning off the Surface Analyst 26
3.1 Intended use and foreseeable unintended use	6	5.13	Removing the battery 26
3.2 Safety instructions	6		
3.3 Main parts	7	6. Purchasable Options	26
3.4 Surface Analyst diagrams and features	7	6.1	Wetting Analytics 26
3.5 Indicator lights	8	6.2	Dyne Mode 27
		6.3	Process Analytics 27
4. Preparation	9	6.3.1	Using Process Analytics 27
4.1 Charging the battery	9	6.3.2	Printing Process Results (Process Analytics Print) 29
4.1.1 Charging the battery with the battery charger	9	6.4	RS232 Output Capability 31
4.1.2 Charging the battery directly with the AC adapter	9	6.5	Data API 31
4.2 Inserting the battery	10	6.6	Auto Profile Selection via QR Code 32
4.3 Handling the Surface Analyst	10		
4.4 Turn on the Surface Analyst	10	7. Cleaning and maintenance	33
4.4.1 Using the Touchscreen	11	7.1	Keeping the Surface Analyst Clean 33
4.4.2 Using the Buttons for Screen Selections	11	7.2	Changing the Cartridge 33
4.5 Understanding the Basic Archer Screens	11	7.3	Maintaining the Surface Analyst 36
4.5.1 The Menu Screen	11		
4.5.2 The Measurement Screen	11	8. Warranty	36
4.6 Doing Performance Checks	11		
4.6.1 Performance Check Surface (PCS)	12	9. Spare parts	37
4.6.2 Performance Check Procedure	12		
		10. Storage	37
5. Use	14	10.1	PCS cards storage and handling 37
5.1 Using the extended controls on the Inspection Head (SA5001 only)	14		
5.2 Operating the Surface Analyst	14	11. Disposing and Recycling	37
5.2.1 Select a User	15		
5.2.2 Prime or Purge the Surface Analyst	15	12. Declaration of Conformity	38
5.2.3 Do a Performance Check if Required	15		
5.2.4 Load a Surface Profile	15	13. Contact information	38

1. INTRODUCTION

Thank you for purchasing the Surface Analyst 3001/5001 by Brighton Science. This user manual is intended for personnel that use the Surface Analyst 3001/5001.

The purpose of this User Manual is to give operating and basic maintenance instructions for the person who uses the Surface Analyst on a regular basis. This manual does not include information for special administrative functions.




The images presented in this manual may differ from the actual appearance of your Surface Analyst.

Always read and understand all safety messages before using the Surface Analyst 3001/5001.

1.1 Copyright

All rights reserved. No part of this publication may be reproduced, transmitted, transcribed, stored in a retrieval system, or translated into any language, in any form or by any means, electronic, mechanical, magnetic, optical, chemical, manual, or otherwise, without the prior written permission of Brighton Technologies Group, LLC.

1.2 Symbols used in the manual



Symbols used	Meaning
 WARNING!	Signal word used to indicate a potentially hazardous situation which, if not avoided, could result in death or serious injury.
 CAUTION!	Signal word used to indicate a potentially hazardous situation which, if not avoided, could result in minor or moderate injury.
NOTICE	Signal word used to indicate a situation which, if not avoided, could lead to damage to the product, but is not related to physical injury.
	Signal symbol used to indicate a situation that should be paid extra attention to, but that is not directly related to product damage or physical injury.

1.3 Symbols on the product

Safety labels are attached to the Surface Analyst 5001 equipment to warn you about potential hazards.



Safety labels include a hazard alert symbol, a signal word, and a written description (when required). The following table describes these terms.

Term	Definition
Hazard alert symbol	Hazard alert symbols give a visual notification of the hazard. Some examples of hazard alert symbols are the following: <ul style="list-style-type: none">General hazard alert symbol Electrocution hazard alert symbol 
Signal word	Signal words describe the level of risk of a particular hazard. The definitions are as follows: <ul style="list-style-type: none">DANGER: This signal word indicates an imminently hazardous situation which, if not avoided, will result in death or serious injury.WARNING: This signal word indicates a potentially hazardous situation which, if not avoided, could result in death or serious injury.CAUTION: This signal word indicates a potentially hazardous situation which, if not avoided, could result in minor or moderate injury.
Written description (as required)	Written special notifications related to the hazard may be included.

Before using the Surface Analyst, read and understand each of the safety labels. The locations of the labels are shown in figure 2.



Figure 2 - Location of safety labels on case

To maintain the safety labels, do the following:

- Keep the labels clear of obstructions so that they are readable.
- Do not remove or tamper with any labels.
- Replace any label that is no longer readable. Contact Brighton Science if you need a replacement.

2. OVERVIEW OF THE SURFACE ANALYST

The Surface Analyst is a portable, manually-operated, hand-held inspection device. It determines surface energy by measuring the contact angle of a water drop deposited on your surface. The Surface Analyst is controlled by Archer, Brighton Science's proprietary software.

2.1 Specifications

Surface Analyst™ 3001/5001	Specification
Weight	1.0 lbs (0.5 kg)
Dimensions (instrument only)	4.4 in × 2.4 in × 9.2 in (11.2 cm × 6.1 cm × 23.4 cm)
Case dimensions	14 in × 17 in × 7 in (36 cm × 43 cm × 18 cm)
Software	Archer (Brighton Science proprietary)
Inspection time	2 seconds*
Noise emission	< 72 dB(A)
Storage capacity	40,000 images

Battery	Lithium Ion 7.4 VDC, 2600 mAh, 19.24 Wh
Battery life expectancy	
Power supply input	100 – 240 VAC, 50 – 60 Hz, 1.2 A
Power supply output	12 VDC, 2.5 A
Battery runtime	5 hours under normal use 6 hours if the instrument is powered on, but the pump is not active
Battery charger input	12 VDC, 2.5 A Charges 1 Brighton Science battery
Battery charger charge time	2 hours

Operating conditions	
Max. temperature	41 °F – 104 °F (5 °C – 40 °C)
Max. altitude	6562 ft (2000 m)
Min. relative humidity	15%
Max. relative humidity	80%, temperatures up to 88 °F (31 °C)
	50%, temperatures up to 104 °F (40 °C)

Fluid cartridge	HPLC-grade water (standard)
Fluid cartridge capacity	1000 measurement
Fluid cartridge shelf life	1 year, unopened in mylar pouch
	6 months, when in use by the Surface Analyst

* Inspection time may be longer with certain options enabled.

2.2 Surface energy and contact angles

The Surface Analyst gives you important information about the surface energy of your product in a fast, easy, non-destructive way.


Knowing the surface energy of your product is important for assuring the success of many processes, including the following:

- Adhesion
- Sealing
- Painting and coating
- Printing
- Hydrophobic applications

What contact angles tell you


The Surface Analyst deposits a drop of fluid onto a surface and measures the contact angle between the drop and the surface.

The contact angle (θ) tells you how much the surface is able to attract other substances.




If the fluid spreads out thinly, that means that the fluid is attracted more strongly to the surface than to itself.

- The surface has a high surface energy.
- The contact angle is low.
- This surface is generally good for bonding applications.



If the fluid "beads", then the fluid is attracted more strongly to itself than to the surface.


- The surface has a low surface energy.
- The contact angle is high.
- This surface is generally not good for bonding applications, but it is good for anti-stick and hydrophobic applications.




2.3 How the Surface Analyst Works

The Surface Analyst measures the contact angle of a fluid drop on your surface to determine the surface energy.


1. The Surface Analyst pulses a stream of several droplets onto the surface. These droplets combine to form one small drop (less than 2 microliters). This process is called Ballistic Deposition.




2. A camera views the drop from above and takes a picture.




3. The Archer software determines the diameter of the drop. Using the known volume of the drop, Archer calculates the contact angle.



4. A large contact angle shows that the surface has low surface energy.



A small contact angle shows that the surface has high surface energy.



3. SAFETY

The following sections list special safety notes that apply to particular components of the Surface Analyst, activities performed while using the Surface Analyst, and environments in which the Surface Analyst is used.

3.1 Intended use and foreseeable unintended use

The intended use of the Surface Analyst is to measure the surface energy properties of a material surface. Do not use the Surface Analyst for any other use.

The Surface Analyst 3001/5001 is intended to only be used by properly trained personnel. It is not to be used by persons (including children) with reduced physical, sensory or mental capabilities, or lack of experience and knowledge, unless they have been given supervision or instructions.

The Surface Analyst 3001/5001 is only intended for indoor use.

The Surface Analyst 3001/5001 is not intended for use in hazardous locations. If you require a Surface Analyst for use in hazardous locations, contact Brighton Science.

3.2 Safety instructions

⚠ WARNING!

Chemical hazard due to misuse. Never attempt to open or tamper with the battery. The battery can expose you to chemicals including nickel, which is known to the State of California to cause cancer and birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov

⚠ CAUTION!

- Chemical hazard due to damage parts. Never use a battery that is bulging or otherwise damaged or deformed. The battery can expose you to chemicals including nickel.
- Chemical hazard due to damage parts. In the event of a cell leaking, never allow the liquid to come in contact with the skin or eyes. If contact has been made, wash the affected area with copious amounts of water and seek medical advice.
- Fire hazard due to overheating. Never expose the batteries to heat or fire. Avoid storage in direct sunlight.
- Electrical hazard. Never allow children to play with the battery or battery charger.
- Never point the inspection head at yourself or anyone nearby.


NOTICE

Risk of product damage.

- Never swing the Surface Analyst around by the tether or wrist strap. Always hold the handle of the Surface Analyst when in use.
- Never use sharp objects like a pen or screwdriver to navigate the touchscreen display. Sharp objects will damage the display. Only use your finger to navigate the touchscreen display.
- Always use the inspection head with care. Rapid movements can damage the tether.
- Always use batteries supplied by Brighton Science.
- Always use the Brighton Science supplied recognized CI II battery charger. Charging the batteries with a different charger could lead to damaged batteries.
- Only use Brighton Science-supplied batteries in the battery charger.
- Do not attempt to recharge non-rechargeable batteries in the battery charger.
- Only use the power supply provided by Brighton Science for powering the Surface Analyst.
- Always store the Surface Analyst and equipment in the storage case when not in use. Storing the Surface Analyst and equipment anywhere else increases the risk of product damage.
- Always keep the fluid cartridges in their mylar pouches until use. Taking out the fluid cartridges prior to use could reduce the shelf life significantly.
- Never expose the fluid cartridges to freezing temperatures. See chapter 'Specifications' for the correct operating conditions.
- Never immerse the Surface Analyst in water or any other liquid.
- Never disassemble the camera, lights, fan filter, or any other parts. Always contact Brighton Science if parts malfunction.
- Never insert anything into the nozzle or valve orifice on the inspection head. Always contact Brighton Science if parts malfunction.
- Environmental risk. Do not dispose of batteries in the trash or in a single stream recycling program. Take all unneeded, spent, or damaged batteries to a facility that specifically handles lithium-ion battery disposal.

3.3 Main parts

The Surface Analyst includes the following equipment packaged in a sturdy carrying case.



1. Storage case
2. Surface Analyst with battery and fluid cartridge installed
3. AC adapter
4. Spare cartridge in foil bag
5. USB flash drive
6. Performance Check Surface (PCS)
7. Battery charger and spare battery
8. Phillips screwdriver
9. Micro USB cable
10. Inspection head

The USB drive contains the following:

- User Manual and Administrator Manual
- Training slides
- Surface Analyst Manager (SAM) with supporting drivers and software
- Software licenses
- End User License Agreement (EULA)
- Data API Guide (for use with the Data API purchasable option)


When you are not using the Surface Analyst, keep all of the equipment in the case.

3.4 Surface Analyst diagrams and features


Your Surface Analyst may vary from the images shown, depending upon the options chosen.



1. Tether
2. Touchscreen display
3. On/Accept buttons
4. Indicator lights
5. Inspection head
6. Inspection attachment (if applicable)
7. Reject buttons
8. Wrist strap
9. Wrist strap anchor



1. Surface Analyst serial number
2. Cartridge bay
3. Cartridge release lever
4. Lockout screw
5. Battery



1. Battery release button
2. USB-A port
3. Micro USB port
4. Power jack

3.5 Indicator lights

When the Surface Analyst is turned on, the indicator lights turns on as follows:

Indicator lights	Meaning
Steady green system indicator	The Surface Analyst is turned on.
Steady green battery indicator	The Surface Analyst is being powered by a sufficiently charged battery.
Flashing green and red battery indicator	The Surface Analyst is being powered by the AC adapter, and the battery is not installed.
Orange battery indicator	The Surface Analyst is being powered by a battery which has minimal charge remaining. A "Low Battery" message is displayed on the screen. Either change batteries or plug the Surface Analyst into a power outlet using the AC adapter.
Steady red battery indicator	The battery is charging.



Figure 7 - Indicator lights

- When you are taking a measurement, the system light changes from green to red.
- By default, the Surface Analyst turns off after 45 minutes of idle time.

4. PREPARATION

Follow the instructions in this chapter for the best operating results. Refer to "Safety instruction" in chapter 3.2 for relevant safety information.

4.1 Charging the battery


You may power the Surface Analyst with either the Brighton Science-provided battery or the AC adapter.

⚠ WARNING!

Read and understand chapter 3.2 for important safety information before using the battery, AC adapter, or the battery charger.

4.1.1 Charging the battery with the battery charger

- Insert the battery (C) into the charger (B).
- ⚠ WARNING!**
Only use the Brighton Sciencesupplied battery and battery charger as listed in "Spare Parts" in chapter 9.
- Push down on the battery to lock it into place.
- Plug the AC adapter (A) into the battery charger.
- Plug the AC adapter into a standard wall outlet.



The meanings of the LED indicator lights (D) are as follows:

Indication LED	Meaning
Two steady green light	The battery is fully charged.
One steady green and one steady red light	Charging is in progress.
One steady green and one flashing red light	The battery is defective and needs to be replaced. Use only batteries supplied by Brighton Science. To order a new battery, see chapter 9.

The charge time is less than two hours. You can also charge the battery inside the Surface Analyst if you attach the AC adapter. See chapter 4.1.2.

4.1.2 Charging the battery directly with the AC adapter

- Plug the AC adapter (A) into the power jack (B).
- i** You can keep the battery installed inside the Surface Analyst, and it will charge while you use the Surface Analyst.
- Plug the AC adapter into a standard wall outlet.



i Due to higher available voltage, the pump will sound louder momentarily when switching from battery to AC.

The battery charge time is less than two hours when it charges inside the Surface Analyst. You can also charge the battery using the battery charger. See chapter 4.1.1.

When the battery is charging inside the Surface Analyst, the battery indicator light changes from red (charging) to green when the battery is charged.



Figure 8 - Battery indicator light

4.2 Inserting the battery

1. Place the battery into its compartment.



2. Press down on the battery until you hear a click.



3. Squeeze the battery and the Surface Analyst together to make sure the contacts are fully engaged.

i Squeeze both ends of the battery to be sure that the contacts are fully engaged.




4.3 Handling the Surface Analyst

Observe the following handling practices:

- Wrap the wrist strap around your wrist to prevent dropping the Surface Analyst while using it. For the convenience of both right-handed and left-handed users, there is a wrist strap anchor on either side of the Surface Analyst where you can attach the wrist strap.
- For models having a tethered inspection head, use care when moving the head. Rapid or extreme movements can damage the tether.
- Always lift and carry the Surface Analyst by the main body. Do not lift or carry the Surface Analyst by the tether or inspection head.

4.4 Turn on the Surface Analyst

Press either one of the two check mark buttons  on the main body to power on the Surface Analyst.

- The Surface Analyst warms up for up to three minutes, if needed.
- The inspection head reaches thermal equilibrium.
- An on-screen timer counts down the maximum time to wait until the Surface Analyst is ready.
- You may view an instructional video by touching the Videos icon on the Warm Up screen.




Figure 9 - Warm up screen

i If your Surface Analyst has temporary features installed, or if you are using a rental instrument, you are notified with a message several days before the trial expires. Contact Brighton Science if you would like to make a purchase. For more information, see chapter 7.

4.4.1 Using the Touchscreen

The Surface Analyst has a pressure sensitive touchscreen. Use only one finger to select buttons and navigate the screens. For the best response, you may find it easiest to use your fingernail to gently tap on the touchscreen.

NOTICE

Do not use anything other than your finger on the touchscreen. Using sharp instruments such as a pen or screwdriver may damage the touchscreen.

4.4.2 Using the Buttons for Screen Selections

Many prompt choices available to a user can be selected from either the touch screen or from the buttons on the Surface Analyst.

When selection by button is available, the text appears in red and green.




Figure 10 - Red and green text is selectable with buttons or with the touchscreen

4.5 Understanding the Basic Archer Screens

Archer is the software that controls the Surface Analyst and performs all the calculations. This section gives an introduction to the basic Archer screens most commonly used.

4.5.1 The Menu Screen



There are three pages of the Menu screen that are available to those logged in as users. The screen page number appears in the lower left corner. You can access a different page of the Menu screen by touching the arrow icons.

The user functions available from the Menu screens are as follows:



- Turning off the Surface Analyst (See chapter 5.12. "Turning off the Surface Analyst")
- Logging in as a user/ changing user passwords (See chapter 5.2.1. "Select a User" and chapter 5.9. "Changing Your Password")
- Selecting a surface profile (See chapter 5.2.4. "Load a Surface Profile")
- Adding a drop note (See chapter 5.7. "Adding a Drop Note")
- Uploading data from the Archer software (See chapter 5.8. "Uploading Data Via USB")
- Finding out information about the license and system parameters (See chapter 5.10. "Viewing the Software License, Settings, and Other Information")

- Doing performance checks (See chapter 4.6. "Doing Performance Checks")
- Viewing informational videos

There are additional pages of the Menu screen available if you are logged in as an administrator. These functions are described in the Administrator Manual.

To get to the Menu screen while in measuring mode, press the X button  or the gear icon .

4.5.2 The Measurement Screen

The Measurement screen is the screen you see while in measurement mode. You can get to the Measurement screen by pressing the check mark button  or by touching the back arrow icon  on page 1 of the Menu screen.








Figure 11 - Measurement screen

- The current user name is displayed in the top left corner.
- The drop note icon  displays the Drop Note menu. See chapter 5.7. "Adding a Drop Note".
- The crosshairs  help you to position the point of drop impact on your surface.
- The drop icon  tells you how many drops you have remaining in the cartridge for taking measurements. This count does not include drops used for purging and performance checks. Touch this icon to view the drop history. See chapter 5.6. "Viewing Drop History" for more information.
- The box in the lower middle of the screen displays the loaded surface profile. Touch this box to go to the Surface Profile menu. See chapter 5.2.4. "Load a Surface Profile" for more information.
- Touching the gear icon  brings you to the first page of the Menu screen.

4.6 Doing Performance Checks

A performance check is recommended at the beginning of each day and as needed to verify that the Surface Analyst is operating at maximum performance.

A performance check consists of the following:

- 1) Measurements are performed on each of the five targets on the PCS card.
- 2) The Surface Analyst automatically analyzes the results from the measurements. If necessary, internal settings are adjusted to ensure proper contact angle readings on the PCS card.

If you have not done a performance check within one week (or for whatever other time period your device has been configured), a message box appears when the device powers up to remind you to do the performance check.




Figure 12 - Performance check reminder message

You may choose to skip the performance check, but that is not recommended. If you do, the reminder message continues to appear upon start-up and when entering measurement mode until you do the performance check.

4.6.1 Performance Check Surface (PCS)

The Performance Check Surface (PCS) is a special card that you must use when doing a performance check.




Figure 13 - PCS (front and back)

The PCS has three circular targets. These targets are printed with a special ink having a controlled and consistent surface energy. There are instructions printed on the back side of the card. To order new cards, see chapter 9. "Spare Parts". You can order online at brighton-science.com.

Special information about the PCS:

- Use a PCS for only one performance check. Discard the card after you complete the performance check.
- Keep unused PCS cards in the provided bag.
- PCS cards expire at the end of the month printed on the card.
- Touch the PCS only in the "Place Thumb Here" area.

i Do not touch the targets. If you do, the performance check will not work properly.

4.6.2 Performance Check Procedure

i If you purchased a custom inspection attachment, make sure to do the performance check using the flat inspection attachment that was installed on your Surface Analyst when it was shipped to you.












Figure 14 - Stock flat inspection attachment


1. Prepare a PCS (Performance Check Surface). Check the expiration date to make sure it has not expired. The card is good through the end of the month printed.

i Be sure not to touch the yellow targets on the card.




<p>2. Have more than one PCS card on hand, as multiple cards may be necessary to complete the performance check.</p> <p>Touch OK when you are ready to start the performance check.</p>		<p>If your PCS is close to its expiration date, a message reminds you to order replacements soon.</p>	
<p>3. Place the Surface Analyst head over the small QR code on the PCS card. Make sure that the crosshairs are near the center of the code and that the entire code fits within the camera field of view.</p>		<p>4. Position the crosshairs over a yellow target on the PCS. Press the check mark button to dispense a drop.</p> <p>i To abort the performance check, touch the gear icon.</p>	
<p>The Surface Analyst scans the code.</p>		<p>5. Five droplets will be deposited on top of each other. Do not move the measurement head until the Drop analysis has begun.</p> <p>i Do not move the measurement head while "Hold in place" is visible.</p>	
<p>If you need to cancel the scan, touch the red box with the "x".</p>			

6. After completing testing on all targets, a message tells you the results of the test:
- Check Passed
- You are finished with the performance check. Touch **OK** to return to the Measurement screen.




OR...

- Purge needed
- A purge is needed. Press continue to begin purge.



OR...

- Performance Check Failed
- The Surface Analyst could not be adjusted to specifications. Contact Brighton Science.



5. USE

5.1 Using the extended controls on the Inspection Head (SA5001 only)






Figure 15 - Surface Analyst 5001 inspection head

- Accept/reject buttons (if included)
- Fan exhaust
- Fan inlet
- LED light diffuser
- Camera
- Valve orifice
- Status light

The green check mark button  on the head behaves in the same way as the button on the main body, except that you cannot power on the Surface Analyst with the button on the head. The check mark button is generally used to take and accept measurements.

The red x button  on the head behaves in the same way as the button on the main body. The x button is generally used to reject and/or retake a measurement.

5.2 Operating the Surface Analyst

The basic steps for operating the Surface Analyst are as follows:

- Turn on the Surface Analyst.
- Select a user (if required).
- Prime the Surface Analyst (if required).
- Do a performance check (if required). A performance check is recommended at the beginning of each day and as needed to verify that the Surface Analyst is operating at maximum performance.

5. Load a surface profile.

6. Take a measurement.

Detailed instructions for these steps are included in the following sections.

5.2.1 Select a User

1. After the Surface Analyst is warmed up, the "Select User" screen appears.




Figure 16 - User screen

- i** The "Select User" screen does not appear if the auto login feature is enabled. If you have auto login enabled, you are instead prompted to prime the system. See chapter 5.2.2. "Prime or Purge the Surface Analyst".
- 2. Select "user1". If your administrator has set up a different user name for you, select that user name. User names are sorted alphabetically, except for the most recently used account which appears first on the list. Use the down arrow to see more user names.
- i** Archer can be set to not show a listing of user names. In this case, you directly type in your user name. See the Administrator Manual for more details.




Figure 17 - User list disabled

3. Enter your password, if prompted.

- i** See chapter 5.9. "Changing Your Password" for how to change your password.

5.2.2 Prime or Purge the Surface Analyst

Priming and purging ensure consistent dispensing.

A prime (also known as a prime shot) is performed upon startup of the Surface Analyst or after ten minutes of inactivity.

A purge is performed upon startup whenever the Surface Analyst has been inactive for over 7 days.

1. A "Prime Needed" or "Purge Needed" message appears on the screen whenever priming or purging is needed.




Figure 18 - Prime Needed message





Figure 19 - Purge Needed message

2. Point the inspection head upward and away from your face, and press the check mark button .
3. After the prime shot (or purge), the Measurement screen is displayed. A short time after that, the screen changes to the Menu screen. The amount of time that the Measurement screen is displayed is called the preview timeout. The default preview timeout is 45 seconds. An administrator can change this time.


5.2.3 Do a Performance Check if Required

If you are prompted to do a performance check, see chapter 4.6. "Doing Performance Checks".


5.2.4 Load a Surface Profile

Before you begin measuring, load a surface profile that is suitable for the surface that you are testing. Depending upon which options are included with your Surface Analyst and how they are configured, you may instead be automatically prompted to choose a surface profile or scan a surface profile QR code. For more information about surface profiles, read the Administrator Manual.

1. On page 1 of the Menu screen, touch **Surface Profile**.




If you are in the Measurement screen, you can also access the surface profiles by touching the box at the bottom of the screen.




2. Choose one of the available surface profiles. Touch **Yes** when prompted to load the selected profile. You may touch the square X icon to exit the Surface Profile screen. If there are more available profiles than fit on the screen, arrows appear to help you navigate to them.


i Surface profiles having a lock icon are created by Brighton Science and cannot be modified



If you want to find out information about a surface profile, touch the question mark box and then touch a surface profile.



If information was created for the surface profile, a description appears. See the administrator manual for instructions for adding profile notes. Touch **Ok** to close the profile note.




5.3 Take a Measurement

A performance check is recommended at the beginning of each day and as needed to verify that the Surface Analyst is operating at maximum performance. See chapter 4.6. "Doing Performance Checks".

NOTICE

The images in this section show a Surface Analyst with the Single-Hand Operation option enabled. This option has extended control buttons in the head, an LED indicator light, and sounds.

1. To take a measurement, press the check mark button or the back arrow in Menu screen page 1 to put the Surface Analyst in measurement mode.



The status light turns orange while the pump is reaching the optimal pressure. When the Surface Analyst is ready to take a measurement, the status light turns white (SA5001 only).



2. Place the inspection head squarely onto the area to be tested. Make sure the inspection attachment or base of the head makes stable contact with the surface.




A red banner reading "Hold in place" appears.


i Do not move the head during the drop deposition. Otherwise, you may get a faulty measurement.



3. Align the crosshairs with the area on the surface that you want to test.



5. You may move the head when the green banner reading "Analyzing" appears.



4. While holding the head steady against the surface, press the check mark button.



If the camera is not able to take a good picture, a message appears for you to take another measurement. If enabled, an audible tone sounds and the indicator light flashes red. To exit this screen, either tap the red banner, press the check mark button, or press the X button.



If Single-Hand Operation is enabled, then you may instead press the green check mark button on the head (SA5001 only).



6. You may see the message "Drop detection OK?" appear on the screen together with flashing dots. This message only appears if SmartDrop is not enabled for the loaded surface profile. See the Administrator Manual for more information. Press the check mark button to accept the drop detection. Press the X button to reject the drop detection and take a new measurement. To know when to accept or reject a drop detection, see chapter 5.5. "Accepting or Rejecting the Drop Detection". If you reject the drop detection, go back to Step 1.



If you have SmartDrop enabled, you are not prompted to accept or reject the drop detection. A message only appears if the drop detection is unacceptable. In this case, you are prompted to re-take the measurement.



When set up to do so, a passing measurement displays in yellow text to warn you if it is close to the allowable limit. If enabled, a "near fail" audible tone sounds after a passing measurement which is close to the fail limit, and the indicator light flashes green and lime.




5.4 View the Measurement Results

The measurement results are displayed on the screen after you take a measurement.


When set up to do so, a "Pass" or "Fail" message appears with a calculated contact angle. The pass or fail result is determined by the allowable contact angle range of the loaded surface profile. If your device is configured for dynes, you will see results displayed in dynes instead of degrees. If enabled, a "passing" audible tone sounds after a passing measurement, and the indicator light flashes green.



If Wetting Analytics is configured in your device (see chapter 6.1. "Wetting Analytics"), then the detection of wettability gives a "Fail" message. A "Fail" is displayed even if the contact angle is within the passing range.



If the "Default" profile is loaded, or if pass/fail limits are disabled, you only see the contact angle result.



If the measurement fails, the allowable limit is displayed. If enabled, a "failing" audible tone sounds after a failing measurement, and the indicator light flashes red.



5.5 Accepting or Rejecting the Drop Detection

A drop detection is the software's determination of the edge of the deposited drop, represented by a pattern of colored dots. The quality of the drop detection is dependent upon things such as surface irregularities and how steady you hold the head during measuring.





Figure 20 - Drop detection

If SmartDrop is not enabled in the loaded surface profile, then the message "Drop detection OK?" displays immediately after you take a measurement. The colored dots flash until you accept or reject the drop detection.

Press the check mark button ✓ to accept a good drop detection. A drop detection is good if the colored dots closely follow the edge of a satisfactorily-deposited drop.

The following images are examples of good drop detections:




i The shape of the blue dots does not need to be a perfect circle as long as the dots follow the edge of the drop, and the drop is not distorted by abnormal features.

Press the X button ✗ to reject the drop detection in the following cases:

- The colored dots do not follow the edge of the drop.
- No clear image of a drop appears on the screen.
- The drop is distorted due to abnormal features in the surface or due to the drop falling off the surface.

The following images are examples of bad drop detections:




i If you have a high number of poorly formed drop detections, contact Brighton Science.

5.6 Viewing Drop History

The Surface Analyst can store several thousand images in its log file.

5.6.1 The Drop History Screen

If you want to view a previous drop image, touch the drop icon  in the Measurement screen to access the Drop History screen.








Figure 21 - Drop History screen

The Drop History screen has the following functions:

- It displays the following information at the bottom of the screen:
 - Drop number (how many drop depositions have occurred with the current cartridge)
 - Active user (only named users appear)
 - Measurement results
 - Drop detection acceptance status
 - Loaded surface profile
 - Date and time of measurement
 - Drop note, if used (See chapter 5.7. "Adding a Drop Note")
- The chart icon  allows you to set a range to chart your results in a graph. See chapter 5.6.2. "Chart Results".
- The back arrow icon  icon sends you back to the Measurement screen.
- The arrows   allow you to view different drop images.


5.6.2 Chart Results

You can review contact angle test results in a graph form for fast and easy trend analysis.



1. Touch the chart icon  in the Drop History screen.




2. Select "Chart results".
Selecting "Go to Result" takes you to a single result only.




3. Select the starting and ending measurement result numbers (r#) by using the + and -.
- i** The r# is a counter that keeps track of measurements. It resets when data is deleted, but it does not reset when a cartridge is changed.



4. The results graph appears showing the contact angle history.




The graph omits points where the drop detection was rejected or where the drop size was too small.






5.7 Adding a Drop Note

A drop note is a note you add to one measurement or a series of measurements. A drop note is stored with all subsequent measurements until you change or delete the note.





1. Go to page 2 of the Menu screen.
Touch **Drop Note**.












<p>2. You have the choice of selecting an existing note, modifying an existing note, deleting an existing note, or creating a new note.</p> <ul style="list-style-type: none"> ▪ Touch one of the listed notes to make it the active note. ▪ Touch Edit Note or Delete Note to edit or delete an existing note. ▪ Touch Add Note to create a new note that will be added to the list. ▪ Touch Custom Note to create a new note that is not saved to the list. 	
<p>3. Type in your note. Touch Done to complete your note.</p>	
<p>4. Touch Yes to accept the note.</p> <p>i The note will be stored with every measurement, beginning with the next measurement.</p> <p>i You can view the current drop note in Menu screen page 2 ⇐ About ⇐ page 2.</p>	
<p>5. If you have an active drop note, you can access the drop note menu directly from the Measurement screen by touching the drop note icon.</p>	
<p>6. To cancel or change the note:</p> <ol style="list-style-type: none"> a. Touch Drop Note on Menu Screen page 2. b. Touch No Note and then OK. 	

5.8 Uploading Data Via USB

The Surface Analyst stores all history data. You can upload this data onto a USB flash drive.

<p>1. Turn on the Surface Analyst. Plug a USB flash drive into the USB port on the top of the Surface Analyst. Only use the USB-A port for uploading data. The micro USB port is for administrator use only.</p>	
<p>2. Go to page 2 of the Menu screen. Touch the USB Upload icon.</p>	
<p>If you have Process Analytics enabled, you have the choice of uploading general measurement results data (Data Export) or the process summary data (Process Summary). See chapter 6.3. "Process Analytics" for more information about Process Analytics.</p>	
<p>3. For data export, you are presented with the settings that will be used for the export. If you are satisfied with the settings, then touch Ok to begin the export. Otherwise, you may touch each of the settings to change its value. If you wish to leave the export menu without exporting, then touch Back.</p>	

Touch the first setting to change which user data to export.		If you leave all the boxes unchecked, then no images will be exported. This results in a faster export. i Drop and Substrate images are the original raw images taken for each measurement. These images are only available if your Surface Analyst has been set to save raw images (not common and not recommended). See the Administrator Manual for more information. Touch Ok to continue.	
Check the boxes of the users to include in the upload. Touch Ok to continue.		Touch the last setting to set the type of export. Toggle this setting to set either Regular Export or Full Export . See "Regular Export vs Full Export" below to learn the difference between the two types of exporting. Touch Ok to begin the export. If you wish to leave the export menu without exporting, then touch Back .	
Touch the second setting to change what time period of data to include.		4. The data uploads onto the USB flash drive. i Archer saves your settings so that you do not need to re-set them the next time you export data.	
<div data-bbox="121 740 237 898"> All data Newest Data X most recent Date range </div> <div data-bbox="270 740 575 951"> All data is exported. Only data since the last export is exported. Choosing this allows you to set how many of the most recent results to include in the export. Set a date range of what data to include. </div>		5. The results and images are stored on the USB drive in the export folder labeled with the date and time. An HTML file is provided with the data export for previewing the data.	
Touch the third setting to change what kinds of images to include.			



Regular Export vs Full Export

A regular export includes the most commonly used information in an easy-to-handle CSV file. The following table describes the information that is included in a regular export:


Regular Export Column Descriptions

Column	Header	Description
A	username	This is the name of the logged-in user.
B	Drop Note	This is the text of the Drop Note.
C	ContactAngle	<p>This is the measured contact angle which was displayed on the screen at the end of the measuring process.</p> <p>i A value of 999 indicates that there was an error in the measurement process and a contact angle could not be measured.</p>
D	profile	This is the name of the surface profile which was active when this measurement was taken.
E	minangle	<p>This is the minimum pass value for the contact angle when dyne mode is not enabled.</p> <p>i When dyne mode is enabled, this value is present in the export but is not used for pass/fail determination.</p>
F	maxangle	<p>This is the maximum pass value for the contact angle when dyne mode is not enabled (this is the standard mode).</p> <p>i When dyne mode is enabled, this value is present in the export but is not used for pass/fail determination.</p>
G	passorfail	A value of "Pass" or "Fail" represents whether or not the measurement was within the pass/fail limits.
H	acceptedorrejected	This represents the user or automated drop acceptance. The values to be expected in this column are "accepted" or "rejected".
I	timestamp	This is the date and time value at the time the measurement was taken. This cell is formatted yyyy-mm-ddThh:mm:ss.nnn.

Column	Header	Description
J	dropnumber	<p>This is the measurement user drop number.</p> <p>i This number decrements on each measurement taken, and resets when the cartridge is replaced (to the maximum number of drops in the new cartridge). For re-analyzed images the drop number from the original inspection is used.</p>
K	cartridgeserial	<p>This is the serial number of the installed cartridge.</p> <p>i This field contains both the serial number entered by the user and the date when the cartridge was installed.</p>
L	WettingImageNumber	(Wetting Analytics only) This gives the image number in a set.
M	WettingDelta	(Wetting Analytics only) This is the difference in contact angle between the current inspection and the first image of the set.
N	WettingPassOrFail	(Wetting Analytics only) This is the result of the wetting analysis (Pass/Fail).
O	Type	This contains information about the type of inspection performed.
P	resultimage	<p>This is the relative path to the result image PNG file.</p> <p>i This field is empty if images are not configured to be saved or if export does not include this image type.</p>
Q	subtractimage	<p>This is the relative path to the subtraction image PNG file.</p> <p>i This field is empty if images are not configured to be saved or if export does not include this image type.</p>
R	subtractanalysis	<p>This is the relative path to the result image with overlaid analysis PNG file.</p> <p>i This field is empty if images are not configured to be saved or if export does not include this image type.</p>
S	rsultanalysis	<p>This is the relative path to the result image with overlaid analysis PNG file.</p> <p>i This field is empty if images are not configured to be saved or if export does not include this image type.</p>

Column	Header	Description
T	dropimage	This is the relative path to the drop image PNG file. <div>  This field is empty if images are not configured to be saved or if export does not include this image type. </div>
U	substrateimage	This is the relative path to the substrate image PNG file. <div>  This field is empty if images are not configured to be saved or if export does not include this image type. </div>


A full export contains all of the same data as a regular export, plus additional data. The information exported in a full export is more comprehensive and the resulting CSV file lists most of the data collected by the Surface Analyst. This data includes image capture and image processing settings as well as other internal settings. It also includes dyne information, if your Surface Analyst is configured for dynes.


 Administrators can also upload the entire results database (DB file). See the Administrator Manual for more information.

5.9 Changing Your Password


If your administrator has required the use of a password to log in, then you can change your password.

Administrators can set standard user-level accounts to require a password or not. However, administrator-level accounts always require a password. See the Administrator Manual for more information.


1. Go to Menu screen page 1  **Users.**




2. Touch **Change PW.**




3. Touch **OK** at the **Change PW** prompt, and then select your user account.


 To cancel, touch **Change PW** again.



4. Enter your old password and new password. Enter the new password again in the **Confirm New Password** field. Touch **Change.**



5. Touch **OK.**



5.10 Viewing the Software License, Settings, and Other Information

To view the software license, settings, and other information, go to page 2 of the Menu screen, and touch **About**.




Figure 22 - About screen page 1

For license information and the End User License Agreement (EULA), touch the square **Legal** icon. Touch **Up** or **Down** to scroll through the different pages on the About screen. The following information is contained on each of the pages:

Page 1

- Serial number of the Surface Analyst
- Archer software version
- Firmware version
- Head firmware version
- Transducer setting
- Fan settings
- Valve use counter
- OS build
- Device IP
- Memory information
- Battery type

Page 2

- Active user
- Loaded surface profile
- Drops remaining/used (Drops used for measurements and purging are counted separately.)
- Auto login status
- Current drop note
- Minimum and maximum pass angles
- Near Fail limit
- Drop detection accept setting
- SmartDrop limit
- Settings for outlier detection
- Current time and time zone
- Cartridge serial number
- Calibration due date
- Number of days since last performance check

Page 3

- Drop dispense settings
- Internal purge settings

Page 4

- General and image process settings (Read the Administrator Manual for more information.)
- Settings for installed purchasable options

Page 5

- Image capture settings (Read the Administrator Manual for more information.)

Page 6

- Purchasable options which are installed on the Surface Analyst

See chapter 5.11. "Viewing Installed Options" for explanations of the codes.

Touch the square **X** icon to exit the About screen.

5.11 Viewing Installed Options

To view which options are installed on your Surface Analyst, go to page 2 of the Menu screen, and touch **About**. Go to page 6 of the About screen.




Figure 23 - About screen page 6

The following table defines the codes:

Purchasable Options Codes

Code	Feature
adac	SmartDrop
aipr	Enhanced Image Processing
batc	Process Analytics
data	Data Collection
dnot	Drop Note
dynd	Dynamic Detection
dyne	Dyne Mode
fawl	Pass/Fail Mode

Code	Feature
mpro	Surface Profiles
pbcrr	Auto Profile Selection via QR Code
pchk	Brighton Science internal use
ppdt	Brighton Science internal use
serl	RS232 Output
shnd	Single-Hand Operation
srft	Wetting Analytics
uloc	Brighton Science internal use
umnt	User Management
vids	Live Videoscope
port	Detachable Portable Option

Options installed on your Surface Analyst are indicated by the word **Unlocked**. Option codes followed by the word **Locked** are not installed. Unlocked options may have an expiration date. Archer alerts you to expiring options ahead of time with a pop-up message. To purchase Surface Analyst features that may be useful for your application, contact Brighton Science.

5.12 Turning off the Surface Analyst

There are two ways to turn off the Surface Analyst:

Option **A**: Hold the check mark button  or X button  down for three seconds.

Option **B**: Touch the "Shutdown" icon on page 1 of the Menu screen.




Figure 24 - Menu screen page 1

⚠ WARNING!

Always store the Surface Analyst in its case when you are not using it.

5.13 Removing the battery

1. While holding in the battery release button (B), push your thumb into the indentation below the outer edge of the battery (A).



2. Lift the battery up and out.



6. PURCHASABLE OPTIONS

The features described in this chapter are available with the Surface Analyst if you purchased them. If you have not purchased these features, but are interested in having them installed on your Surface Analyst, contact Brighton Science.

For a listing of all the purchasable options currently installed on your Surface Analyst, see chapter 5.11. "Viewing Installed Options".

6.1 Wetting Analytics

Wetting Analytics determines if the contact angle decreases over a period of time from the initial dispense.

When Wetting Analytics is turned on, more than one image is captured per measurement taken.

The first image is compared with subsequent images to determine if the drop spreads out beyond the allowed limit (Δ). If a drop spreads out beyond the assigned Δ , then the inspection fails.

Fig. 27 shows the results screens when using Surface Analyst.




Figure 25 - Wetting Analytics Results

When a measurement passes, the delta angle is displayed for reference.

When a measurement fails due to wetting, the delta angle and maximum limit (threshold) are displayed. The initial drop is shown in pink, while the larger blue outline represents the drop after it spreads out after the time delay. The contact angle of the initial drop (before spreading) is also displayed, for reference.

An administrator can enable and disable Wetting Analytics and set parameters. See the Administrator Manual for more information.

6.2 Dyne Mode

Dyne Mode changes the displayed result from contact angle to dynes.



Figure 26 - Dyne Mode


An administrator can enable and disable Dyne Mode. See the Administrator Manual for more information.


6.3 Process Analytics


Process Analytics allows you to set up a workflow ("process") to take a particular number of measurements at several locations on several products. Within this set of measurements, the average value of the measurements and the standard deviation are calculated to determine if the process passes or fails.


An administrator needs to enable and set up Process Analytics within a surface profile. See the Administrator Manual for instructions.


6.3.1 Using Process Analytics

1. Load a surface profile that is configured for Process Analytics. (Menu screen page 1 ) **Surface Profile**)


 If your administrator has configured your Surface Analyst to automatically load the proper surface profile, then you do not have to do this.




2. Press the check mark button  to go into measurement mode. Depending on how the process has been configured, you may see a settings page for the process (such as the one pictured at right), or you may be prompted to enter information.




Fields that appear in bold can be edited by touching them and entering data as prompted. (The ability to enter or edit data is set up by an administrator.)




Touch **Ok** to start the process.




3. While the process is running, the product and measurement numbers are displayed.



4. You are prompted to switch to the next product when the set of measurements for the first product is complete. If Single-Hand Operation is enabled, the LED light in the head alternates between red and green.
- After switching to the new product, either touch **Ok** or press the check mark button to continue.



If at any time you need to cancel the process, touch the gear icon . A message appears, asking if you want to end or continue the process.



5. When the process is finished, a summary displays the results of the process and informs if the process passed or failed. The calculated average contact angle and standard deviation for each product are also displayed.
- A process passes if the calculated average measurement and standard deviation for the entire set of measurements are within the acceptable range.
- Drag your finger on the screen to scroll through the data.

If your Surface Analyst is set up to measure in dynes, then your results are displayed in dynes.


Process PASSED		
Item	Avg	Std Dev
Process	57.3	0.8
#1	57	1
#2	57.5	0.5
<div>Close</div> <div>Graph</div>		

If a process is interrupted, it is labeled as incomplete. The results for the completed portion of the process are displayed, as well as how many measurements were completed.


An incomplete process can pass or fail. If a process (complete or incomplete) fails, then the values that made the process fail are highlighted in red.

Incomplete Process FAILED		
Item	Avg	Std Dev
Process	56	5
#1 (2/2)	56	5
#2 (0/2)		
<div>Close</div> <div>Graph</div>		

6. Touch **Graph** to view a graph of the data. The graph shows you all the contact angle measurements. Vertical bars separate the measurements by product.
- Touch any part of the screen to return to the process summary.
- Touch **Close** to close the summary.



Once the summary screen is closed, you can not view it again. If you want to view the results after closing the summary, upload the data onto a USB drive and choose **Process Summary**. The process data is found in the **completed_process.csv** file. See chapter 5.8. "Uploading Data Via USB".



2. The printer prints the process information.



6.3.2 Printing Process Results (Process Analytics Print)

This feature is only available with the Process Analytics Print option.

Print at the end of a process run

1. Make sure that an appropriate printer is attached to the Surface Analyst (see the Administrator Manual for details).
 At the end of a process run, touch **Print**.

Process PASSED		
Item	Avg	Std Dev
Batch	47.8	2.1
#1	48.7	2.5
#2	47.7	2.5
#3	47	0
Close	Print	Graph

If the process is incomplete, the printout contains the measurements completed as well as the incomplete measurements. Incomplete measurements are reported as "Inc."

```

BTG Labs Surface Analyst: A3321
Process: test Process
Completion Date: 01-25-2019
Completion Time: 11:17:30
Surface Profile: Default Profile
User: admin
Result: Incomplete
Process Avg: Incomplete
Process Std Dev: Incomplete
Process Avg Pass Range: 30.0-70.0
Process Std Dev Tolerance: < 3.0
  
```

Contact Angle Data:

```

=====
Product 1
Measurements : Average : Std Dev
52             : 52.0    : 0.0
52             :         :
  
```


```


Product 2
Measurements : Average : Std Dev
Inc.          : Inc.    : Inc.
Inc.          :         :
  
```

```


Product 3
Measurements : Average : Std Dev
Inc.          : Inc.    : Inc.
Inc.          :         :
  
```

Print at a later time


1. You may delay printing of the process until a later time.
Go to Menu screen page 3  **Process Print**.



2. Select a process from the list.



3. Touch **Print**.



6.4 RS232 Output Capability

RS232 Output allows you to output the measurement results in real time to PLC-type devices. If this option is included with your Surface Analyst, then your device includes a permanently installed USB to RS232 adapter cable that attaches to a PLC-type device.



Figure 27 - Surface Analyst with installed RS232 cable

- i** It is recommended that you keep the Surface Analyst stationary when it is attached to your PLC-type device so that you do not accidentally disconnect the cable.
- i** Make sure that the USB to RS232 cable is connected to the Surface Analyst and to the PLC-type device before you turn on the Surface Analyst. If the cable is not connected (or not working) when the Surface Analyst is started up, then an error message is displayed. This does not stop the Surface Analyst from working, but the serial data will not be sent out. If you see this message, turn off the Surface Analyst, connect the RS232 cable, and turn the Surface Analyst back on.




Figure 28 - RS232 error message

6.5 Data API

The Data API option facilitates the communication of the Surface Analyst with external devices. There are two available methods of communication:


- Communication Option 1: Subscription (real time data)

Users subscribe to specific message types which are sent out in real time as the events happen. For example, a user can subscribe to receive the CSV result line each time an inspection is completed. Other subscriptions are available. See the Data API Guide for more information.

- Communication Option 2: Result Queries (historical data)

Users query the results database to get individual records and images. This method allows the user to perform search queries to find particular sets of records which match desired criteria. Any record which is stored on the Surface Analyst may be retrieved.


If this option is included with your Surface Analyst, then your device includes a permanently installed USB to RS232 adapter cable that attaches to a PLC-type device.



6.6 Auto Profile Selection via QR Code


The Auto Profile Selection via QR Code uses a scan of a QR code to automatically select a surface profile. This feature can be enabled or disabled by an administrator. (See the Administrator Manual for more information.)

1. Go to Menu screen page 1 ➡ **Surface Profile.**




2. Scan the appropriate QR code for the desired surface profile with the Surface Analyst inspection head. If the code is valid and properly read, the surface profile is automatically loaded. You can begin taking measurements.

- i** If you wish to cancel the scan, touch the red X button.




- i** It is recommended that you keep the Surface Analyst stationary when it is attached to your PLC-type device so that you do not accidentally disconnect the cable.
- i** Make sure that the USB to RS232 cable is connected to the Surface Analyst and to the PLC-type device before you turn on the Surface Analyst. If the cable is not connected (or not working) when the Surface Analyst is started up, then an error message is displayed. This does not stop the Surface Analyst from working, but the serial data will not be sent out. If you see this message, turn off the Surface Analyst, connect the RS232 cable, and turn the Surface Analyst back on.

3. If there is an error reading or the scan was cancelled, a list of available surface profiles appears. You may manually select a surface profile to load.



1. When a cartridge has reached its limit of drops, the "Change Cartridge" screen appears. Touch **Yes** to be prompted to begin the cartridge change procedure.

- i** If you choose **Cancel**, you will not be able to do any measurements until the cartridge is changed.
- i** Be sure to have a new cartridge ready before beginning the cartridge change.



7. CLEANING AND MAINTENANCE

Proper cleaning and maintenance is important to keeping the Surface Analyst functioning at peak performance.

NOTICE

Risk of product damage! Never try to perform maintenance by yourself. Contact Brighton Science if any parts malfunctioning.

7.1 Keeping the Surface Analyst Clean

Do the following to keep the Surface Analyst clean:

- If dust builds up on the fan inlet, then gently vacuum to remove the dust.
- Use LCD display wipes to clean the touchscreen.
- Wipe the body of the Surface Analyst with a slightly damp cloth.
- Isopropyl alcohol (IPA) may be used to clean the bottom of the inspection attachment.
- i** Never immerse the Surface Analyst in water or any other liquid.
- i** Never use cleaners that contain ammonia. Never use any abrasive chemicals, solvents or soaps.

7.2 Changing the Cartridge

The Surface Analyst comes with a cartridge installed. You need to replace the cartridge after the drop limit has been reached. See chapter 2.1. "Technical Specifications" for the cartridge fluid capacity. To order new cartridges, see chapter 9. "Spare Parts". You can order online at brighton-science.com.

- i** Do not remove a cartridge from the Surface Analyst unless a message to change the cartridge appears.
- i** Only use a replacement cartridge supplied by Brighton Science. Do not attempt to refill an empty cartridge.
- i** Whenever you remove a cartridge from the Surface Analyst, you cannot reuse the cartridge. You must reinstall a new cartridge.
- i** To view a demonstration video showing how to change a cartridge, go to Menu screen page 3 **Videos**.

2. A message prompts you to check the replacement cartridge for air bubbles. Hold the cartridge up to a light source to see if there are air bubbles present.





Image A shows air bubbles in the cartridge. Image B shows a cartridge with no air bubbles. If no bubbles are present, touch **Continue** on the screen prompt. If you see air bubbles, return the cartridge to Brighton Science for replacement.


- i** Do not use a cartridge that has air bubbles.




3. If Cartridge has a QR code scan it now. Press "X" to manually enter the serial number.




4. If prompted, enter the serial number printed on the new cartridge. Touch **Continue** on the screen prompt.



5. The message "Change Cartridge Now" appears.



6. Remove the lockout screw (E) using the supplied screwdriver. Pull the cartridge release lever (D) down to open the cartridge bay (C).



7. Pull out the old cartridge.




8. Align the new cartridge so that arrow points upward.
Insert the cartridge into the bay all the way.




9. Firmly close the cartridge bay. The release lever returns to its original position.
- i** Make sure that the release lever has returned to its original position before proceeding.




10. Re-install the lockout screw.
Touch **Continue** after you install the lockout screw.




11. A "Purge" message appears.
Point the inspection head upwards, and touch **Continue**.
A stream of fluid dispenses.



12. The cartridge change is complete.
Touch **OK** to begin measurements.



13. A performance check is required after a cartridge change. (See chapter 4.6. "Doing Performance Checks").
Touch **Run Performance Check Now** to begin the performance check. Make sure you have a PCS card ready.



7.3 Maintaining the Surface Analyst

Do the following maintenance to keep the Surface Analyst functioning properly:

- It is recommended to have the Surface Analyst calibrated every year. A message appears on the screen when you log in if the unit is due for calibration. Send in your Surface Analyst to Brighton Science for calibration when prompted.
- ❗ Failure to have your Surface Analyst calibrated may result in unreliable contact angle measurements.
- Always keep the Surface Analyst in its case when you are not using it.
- Send the Surface Analyst to Brighton Science for service if any parts malfunction.
- Handle the inspection head with care.
- ❗ Do not try to remove the camera, lights, fan filter, or any other part.
- ❗ Never insert anything into the nozzle or valve orifice, as you may damage it. If the valve becomes clogged, send the Surface Analyst to Brighton Science.

8. WARRANTY

The following warranty and disclaimers apply to US purchasers:

This Limited Warranty provides the following assurance to the Purchaser of the Surface Analyst™ (Equipment).

(1) Should the Equipment fail to function within normal tolerances due to a defect in materials or workmanship within a period of one (1) year, from the date of delivery of the Equipment to the purchase, BTG Labs will at its sole option: (a) repair or replace any part or parts of the Equipment; (b) provide a functionally comparable replacement Equipment at no charge to Purchaser.

B. BTG's Limited Warranty set forth in Section A (1), is expressly contingent upon the following conditions:

- (1) Purchaser must give BTG written notice of the defect within twenty-four (24) hours of discovery.
- (2) The Equipment must be returned to BTG, within thirty (30) days after discovery of the defect. BTG may, at its sole option, choose to repair the Equipment on site.
- (3) Any attempt by the Purchaser to repair or replace the Equipment, or any part thereof, will render this Limited Warranty null and void, and of no effect whatsoever. Further, and abuse or misuse of the Equipment, whether accidental, reckless or intentional will render this Limited Warranty null and void, and of no effect whatsoever.

C. This Limited Warranty is limited to its express terms. In particular:

(1) Except as expressly provided by this Limited Warranty, BTG IS NOT RESPONSIBLE FOR ANY DIRECT, INCIDENTAL OR CONSEQUENTIAL DAMAGES BASED ON ANY DEFECT, FAILURE OR MALFUNCTION OF THE EQUIPMENT, WHETHER THE CLAIM IS BASED ON WARRANTY, CONTRACT, TORT OR OTHERWISE.

Specifications and Warranty

(1) THE WARRANTIES CONTAINED HEREIN ARE IN LIEU OF ANY AND ALL OTHER WARRANTIES EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE WHETHER ARISING FROM STATUTE, COMMON LAW, CUSTOM OR OTHERWISE. NO EXPRESS OR IMPLIED WARRANTY WITH RESPECT TO PATENTS OR ANY OTHER INTELLECTUAL PROPERTY SHALL EXTEND BEYOND THE PERIOD SPECIFIED IN A (1) ABOVE. THIS LIMITED WARRANTY SHALL BE THE EXCLUSIVE REMEDY AVAILABLE TO ANY PERSON.

(2) This Limited Warranty is made only to the Purchaser of the Equipment, and in no way can be assigned, transferred or in any other way conveyed to any other party. Any conveyance or attempted conveyance of this Limited Warranty will render this Limited Warranty null and void, and of no effect whatsoever.

(3) The exclusions and limitations set out above are not intended to, and should not be construed so as to contravene mandatory provisions of applicable law. If any part or term of this Limited Warranty is held to be illegal, unenforceable or in conflict with applicable law by a court of competent jurisdiction, the validity of the remaining portions of the Limited Warranty shall not be affected, and all rights and obligations shall be construed and enforced as if this Limited Warranty did not contain the particular part or term held to be invalid. This Limited Warranty gives the purchaser specific legal rights. The purchaser may also have other rights which vary from state to state.

(4) No person has any authority to bind BTG, as to any representation, condition or warranty except this Limited Warranty.

(5) INDEMNIFICATION: Except for damages, claims or losses solely due to BTG's acts or omissions, Purchaser, to the extent permitted by law, will indemnify and hold BTG, free and harmless from and any costs, claims or liabilities (including Attorneys' Fees), arising from or relating to losses, claims, injury to or death of any person, including buyer, or for damage to property arising from Purchaser's use and possession of the Equipment or from the acts or omissions of any person or persons, including Purchaser, using or possessing the Equipment.

(6) This Limited Warranty and all terms thereof will be governed by the laws of the State of Ohio, with jurisdiction in the State and Federal Courts located in Hamilton County, Ohio.

(3) The exclusions and limitations set out above are not intended to, and should not be construed so as to contravene mandatory provisions of applicable law. If any part or term of this Limited Warranty is held to be illegal, unenforceable or in conflict with applicable law by a court of competent jurisdiction, the validity of the remaining portions of the Limited Warranty shall not be affected, and all rights and obligations shall be construed and enforced as if this Limited Warranty did not contain the particular part or term held to be invalid. This Limited Warranty gives the purchaser specific legal rights. The purchaser may also have other rights which vary from state to state.

(4) No person has any authority to bind BTG, as to any representation, condition or warranty except this Limited Warranty.

(5) INDEMNIFICATION: Except for damages, claims or losses solely due to BTG's acts or omissions, Purchaser, to the extent permitted by law, will indemnify and hold BTG, free and harmless from and any costs, claims or liabilities (including Attorneys' Fees), arising from or relating to losses, claims, injury to or death of any person, including buyer, or for damage to property arising from Purchaser's use and possession of the Equipment or from the acts or omissions of any person or persons, including Purchaser, using or possessing the Equipment.

(6) This Limited Warranty and all terms thereof will be governed by the laws of the State of Ohio, with jurisdiction in the State and Federal Courts located in Hamilton County, Ohio.

9. SPARE PARTS

The following items are available for purchase. Contact Brighton Science Sales Department at (513) 469- 1800, or orders@brighton-science.com. You can order online at brighton-science.com.

Item		Part number
Fluid cartridge (Water)		11118
USB Drive		11234
AC adapter		11166
Battery Charger		11222
Battery Pack		11438
Three Target Performance Check Surface cards (PCS cards) Pack of 25 Visit brighton-science.com for other quantity options.		12323
Proposition 65 Warning label		11502

To order items and spare parts, visit: brighton-science.com

10. STORAGE

In order to guaranty reliable measurements from the Surface Analyst and reduce the risk of product damage it is important store the Surface Analyst and its accessories properly. Ensure the following points when storing the Surface Analyst and the accessories:

- Keep the Surface Analyst and all equipment in the storage case when not in use.
- Store all the equipment within the temperature and humidity range listed in "Technical Specifications" in chapter 'Specifications'.
- Keep the fluid cartridges in their mylar pouches until ready to use.
- Do not allow the fluid cartridges to freeze.
- Once you put a cartridge in the Surface Analyst, do not remove it until the cartridge is empty. You may not reuse a cartridge if you remove it from the Surface Analyst.

10.1 PCS cards storage and handling

Keep the PCS cards sealed in their original bags with the desiccant packet. When you need to use a PCS, only grasp it by the gray border at the bottom of the card. The PCS cards have an expiration date that is printed on the back side of the card. The cards expire at the end of the month printed.

11. DISPOSING AND RECYCLING



This symbol on the product(s) and / or accompanying documents means that used electrical and electronic products should not be mixed with general household waste. For proper treatment, recovery and recycling, please take this product(s) to designated collection points where it will be accepted free of charge.

Alternatively, in some countries you may be able to return your products to your local retailer upon purchase of an equivalent new product.

Disposing of this product correctly will help save valuable resources and prevent any potential negative effects on human health and the environment, which could otherwise arise from inappropriate waste handling.

Please contact your local authority for further details of your nearest designated collection point.

Penalties may be applicable for incorrect disposal of this waste, in accordance with you national legislation.

For business users in the European Union:

If you wish to discard electrical and electronic equipment, please contact your dealer or supplier for further information.

Information on Disposal in other Countries outside the European Union:

This symbol is only valid in the European Union. If you wish to discard this product, please contact your local authorities or dealer and ask for the correct method of disposal.

Do not dispose of batteries in the trash or in a single stream recycling program. Take all unneeded, spent, or damaged batteries to a facility that specifically handles lithium-ion battery disposal.

12. DECLARATION OF CONFORMITY

We, Brighton Science, declare as manufacturer that the product BC Mobile, has been tested according to all relevant CE standards and regulations and that all tests have been passed successfully. This includes, but is not limited to the RED 2014/53/EU regulation. The complete Declaration of Conformity (and the safety datasheet if applicable) can be found and downloaded via: www.brighton-science.com/security-and-compliance

13. CONTACT INFORMATION

Contact us for general inquiries, technical support, and sales:

Brighton Science

4914 Gray Road

Cincinnati, OH 45232

513.469.1800

service@brighton-science.com

Visit us at brighton-science.com



Brighton Science
4914 Gray Road
Cincinnati, OH 45232

service@brighton-science.com
brighton-science.com
513.469.1800

UK English – Original instructions | V1.2
Manufactured 2022