



Administrator Manual

Surface Analyst™ 5001

Archer 8.15





IMPORTANT SAFETY NOTE!

In addition to reading this manual, read and understand the User Manual for important safety information before using the Surface Analyst.

Failure to do so can result in personal injury, property damage or both.

This English language document is the original Administrator Manual.

Copyright © 2022 Brighton Science.

All rights reserved. No part of this publication may be reproduced, transmitted, transcribed, stored in a retrieval system, or translated into any language, in any form or by any means, electronic, mechanical, magnetic, optical, chemical, manual, or otherwise, without the prior written permission of Brighton Technologies Group, LLC.

Document Version #2

Contents

1 Introduction	6
1.1 Purpose and Scope of this Manual	6
1.2 Important Notes	6
1.3 Contact Us	6
2 Overview of Functions and Settings	7
3 Surface Profile Management	10
3.1 Creating a New Surface Profile	10
3.2 Renaming a Surface Profile	10
3.3 Deleting a Surface Profile	11
3.4 Adding or Changing a Profile Note	11
3.5 Auto Surface Profile Prompting	11
4 General Administrative Functions	12
4.1 Adding and Removing a User	12
4.2 Displaying and Hiding User Accounts	12
4.3 Enabling and Disabling Passwords	13
4.4 Enabling and Disabling Auto Login	13
4.5 Setting Auto Shutdown Time	13
4.6 Changing the Time or Time Zone	13
4.7 Enabling or Disabling Sounds	14
4.8 Setting the Fan Temperature	14
4.9 Updating the Software	14
4.9.1 Updating with a USB Flash Drive	14
4.9.2 Updating with Surface Analyst Manager (SAM)	16
4.9.2.1 Install SAM	16
4.9.2.2 Download and Install the Update	19
4.10 Database Merging	21
4.11 Activating New Purchasable Options	22
5 Cartridge Changing	25
6 Purging	26
7 Results and Image Management	27
7.1 Understanding the Images	27
7.2 Image Saving	29

7.3 Deleting Data	29
7.4 Uploading Data to USB Drive	30
8 The Surface Analyst Process Parameters	31
8.1 Changing the Process Parameters	31
8.2 Image Capture Parameters	32
8.2.1 LED Illumination Level	32
8.2.2 Camera Exposure	33
8.2.3 Drop Settle Time	33
8.3 Image Processing Parameters	33
8.3.1 Image Averaging	34
8.3.2 Image Alignment	35
8.3.3 Drop Center Settings	35
8.3.3.1 Auto Center	35
8.3.3.2 Crosshairs Position	35
8.3.4 Outlier Rejection	36
8.3.5 Ellipse Mode	37
8.3.6 Dynamic Detection Center Finding Parameters	38
8.3.7 Dynamic Detection Edge Finding Parameters	39
8.3.8 Example for Adjusting Image Processing Parameters	41
8.4 General Process Parameters	43
8.4.1 Setting Preview and Pump Timeouts	44
8.4.2 Setting Drop Detection Accept / Reject Options	44
8.4.3 Setting Pass and Near Fail Limits	44
8.5 Re-analyzing the Last Measurement	45
9 Purchasable Options	47
9.1 Wetting Analytics	47
9.1.1 Enabling and Disabling Wetting Analytics	47
9.1.2 Setting Wetting Analytics Parameters	47
9.1.3 Wetting Analytics Results	49
9.2 Dyne Mode	50
9.2.1 Enabling and Disabling Dyne Mode	50
9.2.2 Setting Dyne Parameters	50
9.3 Process Analytics	51
9.3.1 Setting up Process Analytics	52
9.3.2 Understanding the Process Analytics Parameters	54
9.3.3 Setting Up Process Analytics Print	56

9.4 RS232 Output	57
9.5 Data API	58
9.6 Auto Profile Selection via QR Code	58
9.6.1 Enabling and Disabling Auto Profile Selection via QR Code	58
9.6.2 Setting up Auto Profile Selection via QR Code	59
10 Troubleshooting	61
10.1 General Operation	62
10.2 Drop Dispensing	63
10.3 Drop Detections	65
10.4 Results	66

1 Introduction

1.1 Purpose and Scope of this Manual

The purpose of this Administrator Manual is to give advanced instructions for the person who is an administrator for the Surface Analyst 5001.

The images presented in this manual may differ from the actual appearance of your Surface Analyst.

1.2 Important Notes

Important information that is not safety-related is shown in a note message like one of the following:



This note gives information on how to avoid equipment malfunctions or property damage. If you do not follow this note, your warranty may be voided or you may receive incorrect measurements or both.



This note gives other useful, important information.

1.3 Contact Us

Contact us for general inquiries, technical support, and sales:

Brighton Science
4914 Gray Road
Cincinnati, OH 45232
513.469.1800
service@brighton-science.com

Visit us at brighton-science.com

2 Overview of Functions and Settings

The basic functions available to any user are described in the User Manual. To access the advanced functions and settings and perform most tasks in this manual, you must first log in as an administrator. The password is provided in the Welcome Letter which is shipped with the Surface Analyst.

Pages 1-3 of the Menu screen are available to all users, although only an administrator can manage surface profiles on page 1 (Fig. 1.) There are five additional screens available to administrators only (Fig. 2-Fig. 6). See the chapter references listed in the table "Administrator Functions and Settings" on the next page for more detailed explanations.




Fig. 1 - Menu screen page 1
Surface profile rename, copy and delete




Fig. 2 - Menu screen page 4




Fig. 3 - Menu screen page 5




Fig. 4 - Menu screen page 6




Fig. 5 - Menu screen page 7




Fig. 6 - Menu screen page 8

Administrator Functions and Settings

Menu Screen Page #	Function / Setting	Chapter Reference
1	Copy, rename or delete a surface profile	"Surface Profile Management" on page 10
4	Change a cartridge	" Cartridge Changing" on page 25
	Purge the system	"Purging" on page 26
	Set up Process Analytics Only available with the Process Analytics option	"Process Analytics" on page 51
	Enable/disable Dyne Mode and set parameters Only available with the Dyne Mode option	"Dyne Mode" on page 50
	Activate new purchasable options (SCommand)	"Activating New Purchasable Options" on page 22
	Change time and time zone	"Changing the Time or Time Zone" on page 13
5	Re-analyze the last measurement	"Re-analyzing the Last Measurement" on page 45
	Set image saving options	"Image Saving" on page 29
	Delete data	"Deleting Data" on page 29
	Set image processing parameters	"Image Processing Parameters" on page 33
	Merge database files provided by Brighton Science	"Database Merging" on page 21
	Enable or disable automatic drop detection (SmartDrop)	"Setting Drop Detection Accept / Reject Options" on page 44
6	Drop center settings	"Auto Center " on page 35 "Crosshairs Position" on page 35
	Set preview and pump timeouts	"Setting Preview and Pump Timeouts" on page 44
	Set pass and near fail limits	"Setting Pass and Near Fail Limits" on page 44
	Update Archer software	"Updating the Software" on page 14

Menu Screen Page #	Function / Setting	Chapter Reference
7	Enable or disable autologin	"Enabling and Disabling Auto Login" on page 13
	Set the drop settle time	"Drop Settle Time" on page 33
	Set the automatic shutdown time	"Setting Auto Shutdown Time" on page 13
	Enable or disable sounds Only available with Single-Hand Operation option	"Enabling or Disabling Sounds" on page 14
	Set the illumination level of the LED lights and the camera exposure	"LED Illumination Level" on page 32 "Camera Exposure" on page 33
8	Profile menu options--Select surface profile upon startup	"Auto Surface Profile Prompting" on page 11
	Profile menu options--PP designated items	Brighton Science special use
	User menu options--Add/remove user	"Adding and Removing a User" on page 12
	User menu options--Enable/disable passwords	"Enabling and Disabling Passwords" on page 13
	User menu options--Display/hide user list	"Displaying and Hiding User Accounts" on page 12
	Peel Ply Options	Brighton Science special use
	Fan temperature settings	"Setting the Fan Temperature" on page 14
	Add/remove users	"Adding and Removing a User" on page 12


3 Surface Profile Management

Surface profiles are customized collections of settings that are applicable to a particular surface type or application.

You can create new profiles (by copying an existing profile) to save settings that work best for your situation. You can edit and delete any existing profile, except for the Default Profile and locked profiles.

Contact Brighton Science if you need assistance in creating a new profile for a particular surface application. See "Database Merging" on page 21 for more information.

3.1 Creating a New Surface Profile

Menu screen page 1  **Surface Profile**

Create a new surface profile (by copying an existing profile) if you want to save a set of parameter settings.

Touch **Copy Profile**, and follow the directions on the screen.

You are asked if you want to keep the same drop size as the current loaded profile. In most cases, it is recommended to use the same size. If you are measuring a very small surface where the normal drop size is too large, you may choose a smaller number of droplets.



Using very small drop sizes can lead to reduced measurement accuracy. Contact Brighton Science for assistance.

When prompted, you can add a note that is attached to your profile. This note is available to users when they touch the question mark button in the Surface Profiles menu. Touch Edit to add the note.




Fig. 7 - Prompt for adding a surface profile note





Fig. 8 - Profile note viewed from Surface Profile menu


The newly created profile is automatically loaded after you create it. It inherits the previously loaded profile's parameter settings. You can individually edit the profile-specific parameter settings, and they will be saved to your new profile. See "Changing the Process Parameters" on page 31.

3.2 Renaming a Surface Profile


Menu screen page 1  **Surface Profile**

Touch **Rename Profile**, and then select a profile to rename. Enter the new name at the prompt.






You cannot rename the Default profile. You also cannot rename locked profiles that display a lock icon . These are special surface profiles created by Brighton Science.

3.3 Deleting a Surface Profile

Menu screen page 1  **Surface Profile**


Touch **Delete Profile**, and follow the directions on the screen.

 If you delete the currently loaded profile, the Default profile is loaded automatically.



 You cannot delete the Default profile. You also cannot delete locked profiles that display a lock icon . These are special surface profiles created by Brighton Science.

3.4 Adding or Changing a Profile Note

A profile note is a note attached to a surface profile. The profile note is viewable in the Surface Profile menu


Menu screen page 1  **Surface Profile**


Touch the question mark box and select a profile to which you want to either add a profile note or change an existing note. Enter the new profile note in the dialog box.

 .You cannot add or edit profile notes for locked profiles that display a lock icon . These are special surface profiles created by Brighton Science.

3.5 Auto Surface Profile Prompting

You can set Archer to prompt the user to select a surface profile after login and prior to taking a measurement.

Go to Menu screen page 8  **Profile Menu Options**. Set **Select profile on startup** to true. To disable this feature (and allow access to the Measurement screen prior to selecting a surface profile), set to false.

 This function only affects user accounts. Admin accounts are not prompted to select a surface profile when this function is enabled.


4 General Administrative Functions

4.1 Adding and Removing a User

You can add multiple user accounts with passwords to control access to the Surface Analyst. User login activity is stored in the system log.

Menu screen page 8 ➡ **Add / Remove Users**

Touch **Add User** to add a new user. Type in a name for the user and assign a password. You must assign a password to the user, but you can set whether or not the password is required for logging in to a user-level account (see "Enabling and Disabling Passwords" on the next page). Select either "user" or "admin" rights to the new user.



"User" permissions are limited to accessing only Menu screen pages 1-3. "Admin" permissions allow access to Menu screen pages 1-8.

Touch **Remove User** to remove any user.




Users cannot remove their own accounts.

4.2 Displaying and Hiding User Accounts

This feature allows you to display or hide a list of all available user accounts in the Users screen.

Menu screen page 8 ➡ **User Menu Options**. Touch **User List Selection**. Enabling this feature allows selection of a user account from a list at login:



Disabling this feature hides the list of user accounts when a user logs in:





Fig. 11 - Users screen: User List
Selection disabled

4.3 Enabling and Disabling Passwords

Menu screen page 8 ➞ **User Menu Options**

You can set whether or not a password is required for a user to log in. Touch **Passwords for users**. Enable or disable the prompt for a password upon login.

 Administrator accounts always require a password to log in.

4.4 Enabling and Disabling Auto Login

Menu screen page 7 ➞ **Autologin**

The auto login feature enables a user to begin taking measurements without having to log in upon startup of the Surface Analyst. This setting applies to one active user at a time.

Touch **Enable** and select a user from the list.

Other users may log in, but after the Surface Analyst is re-started, the user originally set will be automatically logged in until auto login is changed to a different user or is disabled.

Touch **Disable** to disable the auto login feature.

4.5 Setting Auto Shutdown Time

Menu screen page 7 ➞ **Drop Settle / Autoshtutdown Time** ➞ **Autoshtutdown Time**

Touch **Autoshtutdown Time** to set the time (in minutes) that the Surface Analyst automatically shuts itself off after the set minutes of inactivity.

If you do not want the Surface Analyst to shut down automatically at all, you can disable the feature by entering **0**.

4.6 Changing the Time or Time Zone

Menu screen page 4 ➞ **Time / Time Zone**

Follow the directions on the screen to change the time or time zone.

4.7 Enabling or Disabling Sounds

Menu screen page 7 ➡ **Autologin/Sounds** ➡ **Sounds**

Parameter Scope: Global

If your Surface Analyst is configured with Single-Hand Operation, then you can enable or disable the sounds. Touch **Sounds** to enable or disable.

4.8 Setting the Fan Temperature


Menu screen page 8 ➡ **Peel Ply Options/Fan Temperature** ➡ **Fan Temperature**

Parameter Scope: Global

Touch **Fan** to adjust the temperature or tolerance.


Touch **Temperature** to set the temperature target (in Celsius) for the fan to turn on.

Touch **Tolerance** to set the fan alarm tolerance (in Celsius). When the temperature of the head reaches the setpoint plus the tolerance, you will receive a notification that the temperature is too high.

 In general, it is not advisable to change the fan temperature settings. Doing so may affect the accuracy of the measurement results.

4.9 Updating the Software

When a new release of the Archer software is available, you will automatically be contacted by Brighton Science via email. If you are eligible to receive software updates, the email will contain instructions for you to follow. You can either use a USB flash drive (preferred method) or the Surface Analyst Manager (SAM) software to download the update.

 If you purchased new features for your Surface Analyst, you may activate them by following the instructions in "Activating New Purchasable Options" on page 22.

4.9.1 Updating with a USB Flash Drive

Downloading the latest version of Archer with a USB flash drive is the preferred method for updating.

1. Follow the link provided in the email sent by Brighton Science to download the update .zip file onto a computer. This zip file contains the update as well as the EULA and licensing information.
2. Uncompress the zip file, and copy the .sa_update file into the root of the USB flash drive.
3. Turn on the Surface Analyst.
4. Plug the USB flash drive into the USB-A port of the Surface Analyst.
5. On page 6 of the Menu screen of the Surface Analyst, touch **Software Update from USB**.
6. Touch **Continue** when asked if you want to update software from the USB flash drive.
7. You may see a message asking if you would like to update the Archer software or the head firmware. Choose **Archer** or **Head Firmware**. Only the software or the firmware may be installed at one time. After installation of the first, you will need to select **Software Update from USB** to install the other.




Fig. 12 - Choose Update prompt

8. Select the update file from the list. Usually, only one is visible.
9. A dialog box asks if you want to back up system data before updating. Backing up the system data takes a long time and is not a required step, as the software update will leave the database and results intact. If you want a backup, it is recommended to back up your data before updating.




Fig. 13 - Data backup prompt

10. If you have purchased additional options and/or additional surface profiles, then a message appears asking if you want to apply them. If you would like to apply them, touch **Yes** and follow the prompts. Otherwise, touch **No** to perform just the software update.




Fig. 14 - Software updating options

11. The system updates and reboots.
12. For best results, shut down and restart the Surface Analyst.
13. Go to the About page (Menu screen page 2 \Rightarrow **About**) and check to make sure that the correct software version is displayed.

4.9.2 Updating with Surface Analyst Manager (SAM)

If you prefer not to use a USB flash drive for updating, you must install Surface Analyst Manager (SAM) onto a computer if you have not already done so. The update can then be downloaded onto the computer and then transferred to the Surface Analyst.



The system requirements are as follows:

- Operating system: Windows 7 or later
- Memory: 250 MB RAM, 250 MB hard drive space


4.9.2.1 Install SAM

If you will not be using a USB flash drive to download the update, then SAM must be downloaded and installed on a computer. If you have previously installed SAM, then this step can be safely skipped.


1. Follow the link provided in the email sent by Brighton Science to download SAM onto a computer.
2. Click on the **.exe** file to begin installation
3. Make sure all three checkboxes are checked.
Click **Next**.




4. Click **Install**.




5. Click **Next**.




6. Click **Finish**.




7. Mark the box **I accept the agreement**, and click **Next**.




8. Check a box to create a shortcut, if desired. Click **Next**.




9. Click **Install**.




10. Click **Finish**.
SQLite opens.




11. In the Tools dropdown, select **Options**.



12. Click **File Associations**, and check all three boxes: .db, .db3, .sqlite.
Click **OK**.
Close SQLite.



13. Click **Yes** to reboot.




4.9.2.2 Download and Install the Update

1. Follow the link provided in the email sent by Brighton Science to download the update onto the computer that has SAM installed.
2. From your Downloads folder, drag the

downloaded file to the desktop.


3. Turn on the Surface Analyst.
4. Use the micro USB cable to connect the Surface Analyst with the computer.
5. On your computer, open Surface Analyst Manager (SAM).
Click **Mode**, and then click on **Advanced (ADB)**.



6. Choose **Update Tool Software from Local File**.




7. When the open file folder appears, locate the downloaded update file in the Desktop folder. Click on it, and click **Open**.
8. A progress bar displays during the updating process.



9. If there is a message on the Surface Analyst screen that asks "Allow USB debugging?", check the box to **Always allow from this computer**, and touch **OK** to continue.



10. The Surface Analyst reboots and a message appears that the update is complete
For best results, shut down and restart the Surface Analyst.




11. Go to the About page (Menu screen page 2 ➡ **About**) and check to make sure that the correct software version is displayed.


4.10 Database Merging

Database merging is only used in situations where you are receiving technical support from Brighton Science. For example, if Brighton Science creates a new surface profile for you, that profile needs to be merged into the database on your Surface Analyst. Additionally, there may be a situation where you may need to merge a settings database onto your Surface Analyst. In either case, Brighton Science will send you a database file for you to install.


1. Copy the database file(s) (.db) onto a USB flash drive.
2. Insert the flash drive into the Surface Analyst.
3. Go to Menu screen page 5 ➡ **Image Processing / Merge DB.**



4. Select **Merge DB**.



5. If there is more than one type of database on the USB drive, you are asked which one to merge.




6. When finished, a message displays how many items were merged.




4.11 Activating New Purchasable Options

If you purchased additional options, then you will receive a secure command text file (or a series of commands to enter) from Brighton Science. Follow these directions to activate the new features.

1. Copy the command text file you received from Brighton Science onto a USB flash drive (preferred method). If desired, you may instead enter the command text into the Surface Analyst manually.
2. Menu screen page 4 \Rightarrow **Dyne Mode / SCommand** \Rightarrow **SCommand**




3. To enter the text file with a USB flash drive, insert the USB drive into the Surface Analyst. Select **Load from USB**.



To enter the command text manually, select **Type In**. A keyboard appears for you to type in the text.




4. A **Command successful** message appears when the feature is activated.



5. To view the purchasable options that are installed on your Surface Analyst, go to Menu screen page 2 ➡ **About**. Scroll to page 6.

Options installed on your Surface Analyst are indicated by the word **Unlocked**. Option codes followed by the word **Locked** are not installed. Unlocked options may have an expiration date. Archer alerts you to expiring options ahead of time with a pop-up message.



The following table describes the purchasable option codes.

Purchasable Options Codes

Code	Feature
adac	SmartDrop
aipr	Enhanced Image Processing
batc	Process Analytics
data	Data Collection

Code	Feature
dnot	Drop Note
dynd	Dynamic Detection
dyne	Dyne Mode
fawl	Pass/Fail Mode
mpro	Surface Profiles
pbcr	Auto Profile Selection via QR Code
pchk	Brighton Science internal use
ppdt	Brighton Science internal use
serl	RS232 Output
shnd	Single-Hand Operation
srft	Wetting Analytics
uloc	Brighton Science internal use
umnt	User Management
vids	Live Videoscope
port	Detachable Portable Option

5 Cartridge Changing

Menu screen page 4 ➡ **Change Cartridge**

In general, a cartridge should only be changed when the fluid is depleted and Archer prompts you to change the cartridge. Any user can change a cartridge when prompted by Archer.

If a cartridge needs to be removed at any other time, only an administrator is permitted to do so. The procedure for changing a cartridge is outlined in the User Manual.

ⓘ Whenever you remove a cartridge from the Surface Analyst, you cannot reuse the cartridge. You must reinstall a new cartridge.

6 Purging

Menu screen page 4 ➡ **Purge / Process Analytics** ➡ **Purge**

Some purging happens automatically, such as after a cartridge change or when the Surface Analyst has been idle for an extended period. If the dispensing of your Surface Analyst becomes inconsistent, then a manual purge is recommended.

The types of purging operations include the following:

- Quick purge (short duration)
- Extended purge (medium duration)
- Continuous purge (long duration)

The type of purge recommended depends upon how long the Surface Analyst has been idle. Generally, if you are having issues with dispensing, start with the shortest duration purge and increase to the larger duration purges until the issue is resolved.




Water used for purging and performance checks does not count against the total available drops for measurements listed in the Technical Specifications.


7 Results and Image Management

7.1 Understanding the Images

While in the Measurement screen after taking a measurement, you can view different images of the drop by touching the image on the screen. Each time you touch the image, you see a different image type.


 If you choose to save all analyzed images (see "Image Saving" on page 29), then you can also view these images in the Drop History screen.

Result image




The result image shows the image of the substrate and the drop along with the drop detection and result.

Result analysis image



The result analysis image shows the result image with overlay graphics having the following meanings:



Subtracted image

The subtracted image shows a subtracted image of only the drop. The picture taken with just the substrate has been subtracted from the picture of the substrate and the drop.

Subtracted analysis image




Fig. 18 - Subtracted analysis image

The subtracted analysis image shows the subtracted image with overlay graphics visible.

7.2 Image Saving

Menu screen page 5 \Rightarrow **Image Saving / Delete Data** \Rightarrow **Image Saving**

Image saving allows you to save images for each drop measurement so that you can view them later.

Touch the checkbox to place a checkmark for saving all analyzed images or saving raw images or both.




Fig. 19 - Image saving

Selecting **All Analyzed Images** allows you to view the four different types of images (see "Understanding the Images" on page 27) in the Drop History screen and to upload them onto a USB flash drive.



It is recommended to keep this feature turned on so that you can review all the analyzed images at a later time. If you do not save analyzed images, you will only be able to review or upload the results images.

Selecting **Raw Images** saves the original raw images of the substrate and the drops.



It is generally not recommended to keep this feature turned on, as it increases the processing time and the file sizes are large. Raw images are generally used by Brighton Science Service.

7.3 Deleting Data

Menu screen page 5 \Rightarrow **Image Saving / Delete Data** \Rightarrow **Delete Data**

Touch **Delete Data** to permanently delete all of the results data and images on the Surface Analyst. Make sure you first back up anything you want to keep to a USB flash drive.

7.4 Uploading Data to USB Drive

Insert a USB flash drive into the Surface Analyst before beginning a data upload.

Menu screen page 2 ➡ **USB Upload**

When logged in as an administrator, you are prompted to choose what to upload:





Fig. 20 - USB upload options for administrators

- Choose **Data Export** to upload data (in the form of a CSV file, HTML file, and image files) associated with individual measurements and results. See the User Manual for instructions.
- Choose **Raw Database** to upload the entire contents of the Surface Analyst results database in the form of a DB file.
- Choose **Process Summary** (only available if Process Analytics is included with your Surface Analyst) to upload results of processes performed.
- Choose **Device Configuration** to copy the configuration databases that contain global device settings and profiles.

8 The Surface Analyst Process Parameters

Between the time you initiate a measurement with the Surface Analyst and the time you receive your result is a short period of time. However, there is a lot of processing that Archer does in that time.

Fig. 21 shows the process flow when taking a measurement with a Surface Analyst



The parameters affecting the process which an administrator can set are described in the following chapters:

- "Image Capture Parameters" on the next page
- "Image Processing Parameters" on page 33
- "General Process Parameters" on page 43

8.1 Changing the Process Parameters

You can change the settings of the process parameters in order to optimize the measurement process for your particular surface conditions.



In order to make adjustments to a locked surface profile, you first need to copy it and create a new surface profile. See "Creating a New Surface Profile" on page 10.

All parameters settings are one of the following:

- Profile specific (apply to the current loaded surface profile only)
- Global (apply to the entire Surface Analyst device)
- Can be applied either to the current loaded profile or to multiple profiles

To find out what the parameters are set at for the currently loaded surface profile, go to Menu screen page 2
⇒ **About** ⇒ pages 3-5.




Fig. 22 - About screen



Some of the parameters listed in the About screen are for Brighton Science Service use and are not editable by an Administrator.

Refer to the following sections for information on changing the process parameters:

Topic	Reference
Image capture parameters	"Image Capture Parameters" below
Image processing parameters	"Image Processing Parameters" on the next page
General process parameters such as setting timeouts, SmartDrop, and pass/fail limits	"General Process Parameters" on page 43
Testing the effect of changing parameters using the re-analyze function	"Re-analyzing the Last Measurement" on page 45

8.2 Image Capture Parameters

The parameters in this section affect the image capturing process of the Surface Analyst.

8.2.1 LED Illumination Level

Menu screen page 7 ⇒ **Illumination / Exposure** ⇒ **Illumination**

Parameter Scope: Profile specific

Description: The LED Illumination Level changes the current supplied to the LED lights to make them brighter or dimmer.

Uses: The following are situations to increase Illumination:

- Increase contrast
- Decreases the camera exposure which decreases motion blur and noise

Decrease illumination when you need to decrease the heat of the head.

Considerations: Increasing the illumination increases the heat of the inspection head.

Touch **Illumination** to enter a new illumination (as a percentage of maximum allowable illumination).

8.2.2 Camera Exposure

Menu screen page 7 \Rightarrow **Illumination / Exposure** \Rightarrow **Exposure**

Parameter Scope: Profile specific

Description: Camera Exposure changes the sensitivity of the sensor to light

Uses: Change the Camera Exposure setting when you need to change the brightness of an image.

Considerations: Higher exposures have increased noise.
Lower exposures have a lower overall brightness, but less noise.

Touch **Exposure** to change the exposure on a scale of 1 to 984. The higher the number, the more sensitive the sensor is to light.

In normal operation, it is recommended to use automatic exposure. To set automatic exposure, enter a value of **0**.

8.2.3 Drop Settle Time

Menu Screen 7 \Rightarrow **Drop Settle / Autoshtutdown Time** \Rightarrow **Drop Settle**

Parameter Scope: Can be applied either to the current loaded profile or to multiple profiles

Description: The Drop Settle Time is a necessary time delay which allows the drop to settle between the end of the drop deposition and the image capture.

Uses: If a vapor ring is present and is causing detection problems, a longer drop settle time can decrease the vapor ring by giving it time to evaporate.



Considerations: For longer drop settle times, take extra care to keep the head still during the measurement.

Touch **Drop Settle** to enter the settle time (in seconds).

8.3 Image Processing Parameters

You can set many of the image processing parameters by going to Menu screen page 5 \Rightarrow **Image Processing / Profile Merge** \Rightarrow **Image Processing**.




Fig. 24 - Image processing parameters screen

Touching a parameter name displays a description of its function. Use the arrow icons to scroll up and down to see all of the parameters. Touching a checkbox to add a checkmark enables the function.



All image processing settings are profile specific (apply to the current loaded surface profile only).

8.3.1 Image Averaging

This function is only applicable for Original image processing.

Menu screen page 5 \Rightarrow **Image Processing / Profile Merge** \Rightarrow **Image Processing**

Parameter Scope: Profile specific

Description: Image Averaging captures multiple images for each the substrate and the drop. The pixel intensity of the images are averaged together to form one composite image each for the substrate and the drop.

Uses: Image Averaging reduces noise, particularly in the background of low contrast images. This improves drop detection.




Fig. 25 - No image averaging




Fig. 26 - Image averaging enabled

Considerations: Image Averaging increases the capture time which can increase the likelihood of motion blur.

Image Averaging cannot be used with surfactant detection.



To enable image averaging, touch the checkbox for **Image Averaging**, and then touch **OK**.

8.3.2 Image Alignment

Menu screen page 5 ➡ **Image Processing / Profile Merge** ➡ **Image Processing**

Parameter Scope: Profile specific

Description: In situations where there is movement during the measuring process, Image Alignment moves and rotates the grayscale substrate image so that it aligns better with the grayscale drop image. This allows for more complete removal of the background and a more accurate contact angle calculation.



Uses: Image Alignment is used in situations where it is difficult to keep the inspection head still during measuring.

Considerations: This feature is only recommended when there is movement during measurement. It works best when the background has high contrast features. Image Alignment increases the processing time.

Touch the checkbox for **Image Alignment** to activate this function.

8.3.3 Drop Center Settings

The drop center settings allow you to determine whether the initial center of the drop is calculated (Auto Center) or if the initial center is assumed to be at the crosshairs that appear on the Measurement screen. See "About the Drop Locating Algorithms" on page 1 for more information.

8.3.3.1 Auto Center

Menu screen page 6 ➡ **Scan Radius / Drop Center** ➡ **Drop Center**

Parameter Scope: Can be applied either to the current loaded profile or to multiple profiles

Description: The Auto Center function uses object analysis to determine the center and approximate initial size of the drop.

Uses: It is generally recommended for the Auto Center function to always be enabled.

Considerations: Auto Center may be disabled if the Surface Analyst has difficulty finding the drop center.

Touch **Auto Center** to enable or disable the automatic drop center feature.

8.3.3.2 Crosshairs Position

Menu screen page 6 ➡ **Scan Radius / Drop Center** ➡ **Drop Center** ➡ **Crosshairs**

Parameter Scope: Can be applied either to the current loaded profile or to multiple profiles

Description: Use this function to set the position of the crosshairs on the Measurement screen.




Fig. 29 - Crosshairs on the Measurement screen

Uses: If the drop is consistently not depositing in the center of the screen, you can move the crosshairs to match with where the drop is depositing.

Considerations: If Auto Center is disabled (not generally recommended), the crosshairs are used to determine the center of the drop.

When you touch **Change Crosshairs**, you are asked which direction you want to change.




Fig. 30 - Change crosshairs

Enter a number from 0-99 for either the x-direction or y-direction or both. The position (50, 50) is the center of the screen. The position (0,0) is in the upper left-hand region of the screen. (Note that Archer uses a square image that is centered on the rectangular display.)




Fig. 31 - Example: X=0; Y=50




Fig. 32 - Example: X=0; Y=0








Fig. 33 - Example: X=99; Y=99

8.3.4 Outlier Rejection

Menu screen page 5 \Rightarrow Image Processing / Profile Merge \Rightarrow Image Processing

Parameter Scope: Profile specific

Description: Outlier Rejection replaces dots that are statistically different in position from their neighbors with dots that have a similar distance from the center as the nearest neighbors. The new interpolated dots appear in dark blue, while dots that were unchanged remain light blue.



Uses: Outlier Rejection is used to improve the drop detection so that it more closely follows the edge of the drop.

It is generally recommended to have Outlier Rejection enabled.

Considerations: There are no meaningful downsides to using Outlier Rejection.

Touch the checkbox for **Outlier Rejection** to enable this feature. You may set the outlier percent difference between the location of an individual point and the points around it. Larger values make outlier rejection less sensitive. Smaller values make it more sensitive. A good starting point is a value of 15.

8.3.5 Ellipse Mode

Menu screen page 5 \Rightarrow Image Processing / Profile Merge \Rightarrow Image Processing

Parameter Scope: Profile specific

Description: Instead of calculating the area of the drop with the default method using the location of the found dots, Ellipse Mode calculates the area of a best-fit ellipse using the dots of the drop detection.

Uses: Ellipse Mode filters out dots in the drop detection that do not fit within an elliptical pattern. It can be used with Outlier Rejection.

Considerations: Ellipse Mode smooths out irregularly-shaped drops which can make the contact angle calculation less accurate.

This mode should not be used on rough surfaces such as composites where the expected drop shape is not elliptical.

Touch the checkbox for **Ellipse Mode** to activate this function.



Your Surface Analyst may have Major Axis Ellipse Mode configured. This mode uses the major axis of the best-fit ellipse as the diameter of a circle from which the contact angle is calculated. This method is used in specialized applications where a drop is deposited on a narrow cylindrical object and the contact angle result is affected by the surface curvature. If you think that this method is a good fit for your application, contact Brighton Science for assistance and for special instructions on how to use the Major Axis Ellipse Mode.

8.3.6 Dynamic Detection Center Finding Parameters

Menu screen page 5 **Image Processing / Profile Merge** **Image Processing**

Parameter Scope: Profile specific

Description: The set of parameters listed in the following table control the behavior of the center finding algorithms.

Parameter	Application
Center Minimum Diameter	<p>Settings: Min: 0, Max: 999 Expressed in pixels of diameter (image is 480 x 480 pixels). Default: 15</p> <p>Description: Found objects which have smaller diameters in pixels (width or height) than this parameter will be removed during the non-relevant object removal process.</p> <p>Uses: Filter out noise and satellites (small droplets).</p> <p>Considerations: This parameter is useful when the main drop is off center and there are satellites (small droplets) which occur in the center.</p>
Center Maximum Diameter	<p>Settings: Min: 0, Max: 999 Expressed in pixels of diameter (image is 480 x 480 pixels). Default: 370</p> <p>Description: Found objects which have larger diameter in pixels (width or height) than this parameter will be removed during the non-relevant object removal process.</p> <p>Uses: Filter out artifacts from movement or uneven lighting.</p> <p>Considerations: This setting may need to be increased when working with extremely low contact angle inspections.</p>

Parameter	Application
Center Merge All	<p>Settings: True, False Boolean value representing the merge method. Default: False</p> <p>Description: Treat all remaining objects as a single object for the purpose of center location and drop size estimates. This takes the minimum and maximum dimensions of the individual object bounding boxes and makes a new bounding box which holds all the objects then uses that resulting larger box as the drop center and size.</p> <p>Uses: When movement, lighting artifacts, or satellites are not expected to be present then this can be an easy way to merge objects which form a single drop (due to low contrast or lighting issues).</p>
Center Merge Distance	<p>Settings: Min: 0, Max: 500 Expressed in integer pixels of growth (image is 480 x 480 pixels). Default: 7</p> <p>Description: Objects are grown by this amount and then whatever objects are left over after the growth cycle are then shrunk by this amount. Nearby objects are often merged into an unrecognizable mass which then shrinks back to the original size with a connection between the original found objects.</p> <p>Uses: This is useful when there is expected that there might be clutter or movement artifacts which should be ignored, but the central drop is broken into pieces which need to be merged.</p>

8.3.7 Dynamic Detection Edge Finding Parameters

Menu screen page 5 ➡ Image Processing / Profile Merge ➡ Image Processing

Parameter Scope: Profile specific

Description: The set of parameters listed in the following table control the behavior of the drop edge finding algorithms.

Parameter	Application
1 Near, 1 Far	<p>Settings: Near Min: 0, Max: 1 Far Min: 0, Max: 2 Multiplier based upon the center locator size estimation. Default: Near 0.5, Far 1.5</p> <p>Description: The 1 Near, 1 Far parameters use the center finding estimated size . The edge tools will only return results in between the two circles generated by these parameters.</p> <p>Uses: The Near Pass Multipliers limit the chance of finding an edge inside the drop. The Far Pass Multipliers limit the chance of finding an edge outside the drop.</p> <p>Considerations: Normally the near parameter will be a number < 1 so it is inside the estimated drop size. Normally the far parameter will be a number > 1 so it is outside the estimated drop size.</p>
2 Near, 2 Far 3 Near, 3 Far	<p>Settings: Near Min: 0, Max: 1 Far Min: 0, Max: 2 Multiplier based upon the last edge finding pass. Default: 2nd Near 0.55, 2nd Far 1.4 Default: 3rd Near 0.7, 3rd Far 1.3</p> <p>Description: These parameters use the last finding pass. The edge tools will only return results in between the two ellipses generated by these parameters.</p> <p>Uses: The Near Pass Multipliers limit the chance of finding an edge inside the drop. The Far Pass Multipliers limit the chance of finding an edge outside the drop.</p> <p>Considerations: The third pass near and far parameter is also used when more than three passes are required for the drop edge to become stable. Normally the near parameter will be a number < 1 so it is inside the estimated drop size. Normally the far parameter will be a number > 1 so it is outside the estimated drop size.</p>

Parameter	Application
Invert Finding	<p>Settings: Enable, Disable Default: Disable</p> <p>Description: This changes the edge finding so it looks for the opposite intensity edges from normal finding.</p> <p>Uses: This might be useful if the drop is always lighter than the background and so a white ring is always present at the edge of the drop.</p> <p>Considerations: This parameter is rarely used.</p>
Edge Width Filter	<p>Settings: Min: 1, Max: 99 – MUST BE AN ODD NUMBER Number of pixels to be averaged together across the width of the edge Default: 15</p> <p>Description: This parameter provides filtering along the perimeter of the drop edge and will provide smoothing to the location of the found dots.</p> <p>Uses: This provides the ability for bridging small gaps in the drop edge.</p>
Edge Length Filter	<p>Settings: Min: 3, Max: 99 – MUST BE AN ODD NUMBER Number of pixels to be averaged together across the length of the edge Default: 15</p> <p>Description: This parameter is the kernel size used in the initial derivative calculation to find edges. This functionally works as a filter along the length of the edge.</p> <p>Uses: This parameter makes the edge less sensitive to noise and "white snake" type edges parallel to the drop perimeter.</p>

8.3.8 Example for Adjusting Image Processing Parameters

The surface profiles in your Surface Analyst have been optimized and in most cases will not need any adjustments to the image processing. However, there may be some rare applications where adjustments may enhance the consistent drop detection for difficult situations. This section gives an example of a situation where adjustments to the center finding and edge detection parameters may be helpful.



In order to make adjustments to a locked surface profile, you first need to copy it and create a new surface profile. See "Creating a New Surface Profile" on page 10.

Example Problem:

The drop has low contrast and three distinct dark areas which do not create a nice center location.




Fig. 38 - Drop image with low contrast




Fig. 39 - Subtraction image

The drop was incorrectly located inside the actual drop.




Fig. 40 - Original drop detection

Example Solution #1:

Increase the center merge distance for the center finding so that it treats all of the found objects (shown in Fig. 40 as shaded purple areas) as one object.

Changing the center merge distance from 7 pixels to 21 pixels merges all of the found objects into one, as shown in Fig. 41. This results in a reasonable center finding.





Fig. 41 - Adjusting the center merge distance

Example Solution #2

Increase the edge filtering to smooth the drop.

Changing the edge width filter to 35 bridges the gaps along the edge of the drop, and changing the edge length filter to 21 helps reduce noise inside the drop, as shown in Fig. 42.




Example Solution #3

Adjust the pass multipliers.

For drops like this where most of the edge is found well, only the 3rd near multiplier needs to be changed. Changing the 3rd near multiplier from 0.8 to 0.95 pushes the found locations out from the center and further smooths the drop detection. The arrow in Fig. 43 shows the location of the new 3rd pass near multiplier (thin green ellipse).

! For a near pass multiplier of 0.95 to work the actual drop needs to have a smooth outline. Drops on rough surfaces such as composites would not work well with a near pass multiplier this large.



8.4 General Process Parameters

The parameters described in this section are general parameters that affect the behavior of the Surface Analyst during operation.

8.4.1 Setting Preview and Pump Timeouts

Menu screen page 6  **Preview / Pump Timeout**

Parameter Scope: Global

Preview Timeout

Touch **Preview Timeout** to set the time (in seconds) that a user can be in the Measurement screen before the screen reverts to the Menu screen and the pump shuts off. You can disable the preview timeout by entering **0** so that it will not time out at all.

Pump Timeout

Touch **Pump Timeout** to set the time (in seconds) that the pump will run after a measurement is taken. The screen remains as the Measurement screen after the pump times out.

8.4.2 Setting Drop Detection Accept / Reject Options

Menu screen page 5  **SmartDrop / Wetting Analytics**  **SmartDrop**

Parameter Scope: Can be applied either to the current loaded profile or to multiple profiles

This function sets how the drop detections are accepted or rejected.

The following choices are available:

- **User Accept / Reject:** The user must manually accept or reject the drop detection when prompted by the Surface Analyst. SmartDrop is disabled.
- **SmartDrop:** Enables SmartDrop. The drop detection is accepted or rejected automatically by Archer. If the drop detection is unacceptable, a message is displayed for the user to take another measurement.
- **Accept all:** All drop detections are accepted automatically.

SmartDrop settings

If you choose **SmartDrop**, then there are additional settings available.

Touch **This Profile Only** or **All Profiles**

- Choose **Use Default** if you want to accept the default limits for the automatic accept / reject function.
- Choose **Specify (Advanced)** if you want to set your own limit.
 - Set the accept / reject limit to a value between 0.1 and 1.0.
 - The number you set is the ratio of the perimeter of the drop detected (sum of the polygon sides) to the perimeter of a circle with the same area.
 - The default value is 0.7.

8.4.3 Setting Pass and Near Fail Limits

Menu screen page 6  **Pass/Near Fail Limits**

Parameter Scope: Profile specific

Pass Limits

Touch **Pass Limit** to set the maximum and minimum limits. If the Surface Analyst calculates a result that falls inside these limits, it displays a green "Pass" message along with the result. If the result falls outside these limits, it displays a red "Fail" message along with the result.



If you do not want a pass or fail message to display during measurements, then change the minimum angle to 0 and the maximum angle to 180. (For dynes, enter a minimum of 0 and a maximum of 200).

Near Fail Limits

Touch **Near Fail Limit** to warn users that results are passing but are nearing the maximum or minimum allowed value. Enter a value for a distance from your minimum and maximum acceptable values that will trigger the warning. The Surface Analyst displays a yellow "Pass" message when the result is in the near fail warning range.

The following examples show a pass limit of 0-80° with a near fail limit of 1. Fig. 44 shows how the result appears when the result is within the pass limit and outside of the near fail limit. Fig. 45 shows how the result appears when the result is within the pass limit and within the near fail limit.



8.5 Re-analyzing the Last Measurement

Menu screen page 5 ➡ **ReAnalyze Last Measurement**

Use ReAnalyze Last Measurement to test out different processing parameters to see the affect they have on a single measurement.

1. Take a measurement. In this example, Outlier Rejection is disabled.
2. Change one or more processing parameters as desired. In this example, Outlier Rejection is changed to enabled.



3. Go to **ReAnalyze Last Measurement** to see the difference made by changing the parameter.



When images are re-analyzed, the drop number stays the same, but the results number (r#) is incremented. The original drop data as well as the re-analyzed drop data are stored in the database.

9 Purchasable Options

The features described in this chapter are available with the Surface Analyst 5001 if you purchased them. If you have not purchased these features, but are interested in having them installed on your Surface Analyst, contact Brighton Science.

For a listing of all the purchasable options currently installed on your Surface Analyst, see "Activating New Purchasable Options" on page 22.

9.1 Wetting Analytics

Wetting Analytics determines if the contact angle decreases over a period of time from the initial dispense. Wetting Analytics works by taking an additional image of the drop after the normal drop image. The contact angles of the two images are compared. If a surface has high wettability, the drop continues to spread out on the surface after the drop deposition.

9.1.1 Enabling and Disabling Wetting Analytics

Menu screen page 5 \Rightarrow **SmartDrop / Wetting Analytics** \Rightarrow **Wetting Analytics**


Touch **Enable / Disable** to turn Wetting Analytics on or off for the current loaded profile.

9.1.2 Setting Wetting Analytics Parameters

The parameters for Wetting Analytics have been pre-set, but you can change them, if desired.

The overall time delay ("t") is the time elapsed (in seconds) between when the first and last images of the drop are taken.

The delta is the contact angle difference between when the drop is first deposited and after it has settled after a "t" second delay. The delta threshold is the value at which the Surface Analyst fails the measurement for wetting.



Menu screen page 5 \Rightarrow **SmartDrop / Wetting Analytics** \Rightarrow **Wetting Analytics**

Parameter Scope: Profile specific

Delta threshold

Touch **Change Delta** to change the delta threshold. Increasing this value decreases the sensitivity of Wetting Analytics.

Time and interval

Touch **Change Capture** to access parameters that control the time delay between the first image and last image taken. You can set a time delay that captures images at the beginning and end of the time span, or you can set a time delay that captures several images within the time span.

Touch **Overall Time** to change the time from the first image taken to the last image taken. This is the amount of time used for the overall wetting pass/fail determination. Increasing the overall time increases the sensitivity of Wetting Analytics.



Touch **Image Interval** to set the length of time between individual captured images in the overall time span. This parameter is useful if you want to gain more granular information about how the drop wets the surface over time. This information is stored in the Surface Analyst database and can be exported.

- Due to camera frame rate limitations, intervals are available in 66.7 ms increments.
- Setting the interval to 0 disables the capture of any additional images between the initial and final images. This is the recommended setting for most applications.
- The number of images is calculated from the overall time and the interval selected.


Example:

Set an overall time of 2 seconds, with intervals having a time of 200 ms each.


1. Set the **Overall Time** to 2 seconds




2. Set the **Image Interval** to 3
(200 ms ÷ 66.7 ms/increment = 3 increments)



3. The capture information is displayed.




For a total time of 2 seconds, and intervals of 200 ms, the number of actual images that will be captured is 11, as illustrated in .Fig. 47.



The maximum number of image captures per measurement is 200.

9.1.3 Wetting Analytics Results

Fig. 48 shows the results screens when using Surface Analyst.



When a measurement passes, the delta angle is displayed for reference.

When a measurement fails due to wetting, the delta angle and maximum limit (threshold) are displayed. The initial drop is shown in pink, while the larger blue outline represents the drop after it spreads out after the time delay. The contact angle of the initial drop (before spreading) is also displayed, for reference.

Archer stores results information for the measurements using Wetting Analytics. Fig. 49 shows the database results for a single measurement having a 3-second overall time, and an image interval of 667 ms (image interval set to 10). See "Uploading Data to USB Drive" on page 30 for how to upload the results from the Surface Analyst.

CD	CE	CF	CG	CH	CI
WettingImagesTotal	WettingImageNumber	WettingMsSinceFirst	WettingDelta	WettingPassOrFail	WettingDeltaAngleTolerance
6	1	0	0		10
6	2	667	3.5		10
6	3	1333	4.9		10
6	4	2000	5.8		10
6	5	2667	6.3		10
6	6	3000	6.6	Pass	10

Fig. 49 - Wetting Analytics results

9.2 Dyne Mode

Dyne Mode changes the displayed result from contact angle to dynes.

9.2.1 Enabling and Disabling Dyne Mode

Menu screen page 4 \Rightarrow **Dyne Mode / SCommand** \Rightarrow **Dyne Mode**

Touch **Enable/Disable** to turn Dyne Mode on or off . Touch **Only Current Profile** to affect the current loaded profile only. Touch **ALL profiles** to have the change affect all profiles.

9.2.2 Setting Dyne Parameters

Menu screen page 4 \Rightarrow **Dyne Mode / SCommand** \Rightarrow **Dyne Mode** \Rightarrow **Parameters**


Parameter Scope: Can be applied either to the current loaded profile or to multiple profiles

You can change parameters that alter the dynes calculation based upon your specific surface application.

The dynes parameters (A,B,C,D) are derived by lab testing of a particular surface with differing surface treatments applied. For each surface condition, a dynes measurement is plotted against the contact angle result in an Excel spreadsheet. A best fit polynomial is derived in the form:

$$\text{Dynes} = Ax^3 + Bx^2 + Cx + D.$$

An example graph of dynes and contact angle for a particular glass surface is shown below:



Since the best fit polynomial in this example is $y = 0.0146x^2 - 2.0236x + 101.09$, the parameters for this particular surface profile are entered as follows:

Dyne Parameters

A = 0.0

B = 0.0146

C = -2.0236

D = 101.09

Cancel OK



Fig. 51 - Dynes parameters

⚠ Only use the correct parameters that are based upon verified lab testing. Otherwise, your results will be inaccurate.

9.3 Process Analytics

Process Analytics allows you to set up a workflow ("process") to take a particular number of measurements at several locations on several products. Within this set of measurements, the average value of the measurements and the standard deviation are calculated to determine if the process passes or fails.

Fig. 52 and Fig. 53 show the results of an example set of six measurements, where two measurements were taken on each of two separate products.





Archer supports up to 99 products and 99 measurements per product.

See the User Manual for detailed instructions on how to use Process Analytics.





9.3.1 Setting up Process Analytics

1. You may set up one process per surface profile. Before setting up a process, load the desired surface profile.
2. Go to Menu screen page 4 \Rightarrow **Purge / Process Analytics** and touch **Process Analytics** to set up a process for your desired application. Set the **Process Enabled** parameter to **true** in order to enable Process Analytics for the loaded surface profile.
3. Touch each parameter to change its setting. Each of these parameters is customizable (see "Understanding the Process Analytics Parameters" on page 54 for more details). Use the arrow button to scroll all the way to the end.
4. Touch **Ok** when you are finished.



Process Analytics optional settings

The following table lists the optional settings for Process Analytics. All of these settings can be found in Menu screen page 8 \Rightarrow **Profile Menu Options**.

Task	Instructions	
Prompt selection of a surface profile for each process.	<p>Set Select profile each process to true.</p> <p>Whenever a new process is loaded, the user is prompted to select a surface profile.</p>	
Allow a user to only see surface profiles that are enabled for Process Analytics.	<p>Set Filter process profiles to true.</p> <p> This setting does not affect what a user with admin permissions can see. Admin accounts are always able to view all available surface profiles.</p>	
Add a prefix to label all surface profiles set up for Process Analytics.	<p>Touch process profile prefix, and type in your desired prefix.</p> <p>In this example, the prefix is "Batch".</p> <p>In the Surface Profiles menu (Menu screen page 1), all of the profiles that are set up for Process Analytics show the prefix.</p>	

9.3.2 Understanding the Process Analytics Parameters

There are several parameters that control how a process is performed and what metadata is included with the process. These may be set in Menu screen page 4 \Rightarrow **Purge / Process Mode** \Rightarrow **Process Analytics** (see "Setting up Process Analytics" on page 52).




Fig. 54 - Process Analytics parameters


A complete listing of these parameters is shown in the following table :

Process Analytics Parameters

Parameter	Meaning
Process Enabled	Set this value to true to enable the Process Analytics function for the loaded surface profile. Set this value to false to disable Process Analytics for the loaded surface profile.
# Products	The total number of different products on which measurements will be taken in each process
# Measurements	The number of measurements to take on each product
Process Max Avg	The maximum allowable average result
Process Min Avg	The minimum allowable average result
Process Max StdDev	The maximum allowable standard deviation for all measurements
# Wetting Fail Allowed	The maximum number of allowable wetting failures. (To be used with the Wetting Analytics purchasable option)
Fields 1-5	Customizable fields that allow you to enter a descriptor and a value

Options within the parameters

By touching each parameter, you can access additional options that control how the parameter information is entered and displayed.



The following table lists the available options for each parameter. Setting an option to **true** enables that option. Setting an option to **false** disables it.

Process Analytics Parameter Options

Option	Meaning
Show user (set to true or false)	Determines whether or not this parameter is visible to the user Note: This setting is recommended to be set to true when a user enters parameter values.
Name	Label that describes the parameter
Default data	Sets the default value of the parameter
User Editable (set to true or false)	Determines whether or not a user can edit the parameter set values
From Barcode (set to true or false)	Uses a QR code scan to fill in the parameter values See "Notes about using QR codes" below
Barcode Separator	What character (if any) is used to separate information in the QR code (only used when From Barcode is set to true)
Barcode Location	Designates the location in the QR code where the parameter value can be found (only used when From Barcode is set to true)
Barcode Length	If no QR code separator is used, designates the character length of the parameter value within the QR code (only used when From Barcode is set to true)


Notes about using QR codes


The following recommendations apply if you use a QR code to enter data:

- Data within the barcode must be ordered consistently and should have separators (such as a commas) between them. If separators are not used, then the field length (number of characters) for

each type of data must be consistent.

- The recommended size of a QR code is 7 mm square.

 When using the QR code scan functionality during a process run, the scan can be overrided by touching the red X during the barcode scan. The user is then prompted to enter the data manually.




9.3.3 Setting Up Process Analytics Print

This feature is only available if you purchased the Process Analytics Print option. You must supply the printer.

Printer and cable requirements

- For best results, use an Epson TM-U220B printer with serial interface and integrated cutter. Process Analytics Print has been optimized for this particular printer
- A null modem cable (maximum 50 ft) for use with the Epson TM-U220B printer (9 pin female to 25 pin male) is required.

 If you choose a different printer, it must support Epson ESC/POS commands.

Printer connection

- The Surface Analyst comes installed with a USB to RS232 9 pin male adapter cable to attach to the printer cable, as shown in Fig. 57.



Fig. 57 - Surface Analyst with installed RS232 cable

- The recommended RS232 configuration for the printer is as follows:
 - 9600 Baud
 - 8 bits
 - 1 stop bit
 - No parity
 - No hardware shaking (set to XON/XOFF).



Process Analytics Print is not available if you purchased the RS232 Output option.

9.4 RS232 Output

RS232 Output allows you to output the measurement results in real time to PLC-type devices

Your Surface Analyst includes the RS232 cable (shown in Fig. 57) and comes pre-configured with one of the following configurations:

- Standard configuration
 - A single number is provided followed by a carriage return and line feed.
 - Data is transmitted immediately when the user sees the pass/fail results.
- Verbose mode output
 - This mode outputs more data (similar to what is written to the database).
 - Use this mode if you are willing and able to parse more data.
 - Data is transmitted after the user dismisses the screen where the pass/fail results appear.




This option is not available if you purchased the Process Analytics Print option.

Messages and Errors

When a USB to RS232 cable is first used, a message box may appear. Check the box, and click OK. The Surface Analyst will remember the setting and not prompt you again.



If the cable is not connected (or not working) when the Surface Analyst is started up, then an error message is displayed. This does not stop the Surface Analyst from working, but the serial data will not be sent out. If you see this message, turn off the Surface Analyst, connect the RS232 cable, and turn the Surface Analyst back on.



9.5 Data API

The Data API option facilitates the communication of the Surface Analyst with external devices. There are two available methods of communication:

- Communication Option 1 : Subscription (real time data)

Users subscribe to specific message types which are sent out in real time as the events happen. For example, a user can subscribe to receive the CSV result line each time an inspection is completed. Other subscriptions are available. See the Data API Guide for more information.

- Communication Option 2: Result Queries (historical data)

Users query the results database to get individual records and images. This method allows the user to perform search queries to find particular sets of records which match desired criteria. Any record which is stored on the Surface Analyst may be retrieved.

For further information and setup instructions, refer to the User Manual and the Data API Guide that are included on the USB flash drive.



This option is not available if you purchased the Process Analytics Print option.

9.6 Auto Profile Selection via QR Code

This option allows an automatic selection of a surface profile via a QR code scan.

9.6.1 Enabling and Disabling Auto Profile Selection via QR Code

If Auto Profile Selection via QR Code is already set-up to read a QR code, go to Menu screen page 8 ➡ **Profile Menu Options**.

Set **Barcode read for profile** to **true** to enable QR code scanning for surface profile selection. To disable this feature, set **Barcode read for profile** to **false**.

9.6.2 Setting up Auto Profile Selection via QR Code

In most cases, Auto Profile Selection via QR Code is already set up for you in the Surface Analyst. Follow these instructions if you want to set-up this feature on your own.

Supply a QR code for each surface profile


Create a QR code that contains at least the name of the surface profile you desire to scan. You can optionally include a note that will be saved by Archer as a drop note. (See the User Manual for information about using drop notes.) Other information can also be included in the code, but it will be ignored by Archer.

QR code requirements

- Each QR code must contain the exact name (case sensitive) of one of the available surface profiles loaded on the Surface Analyst as listed in Menu screen page 1 ➡ **Surface Profiles**.
- Each QR code may contain an optional drop note. If one QR code includes a drop note, then all QR codes include a drop note.
- Data within the barcode must be ordered consistently and should have separators (such as a commas) between them. If separators are not used, then the field length (number of characters) for each type of data must be consistent.
- The recommended size of a QR code is 7 mm square.

Example


Fig. 58 shows a sample QR code generated using a free on-line application. In this example, the name of the surface profile is "Test Surface Profile", and the drop note text is "Drop note example". A comma separates the drop note from the surface profile name.



Surface Analyst Setup

The setup instructions refer to the example in Fig. 58 .

1. Go to Menu screen page 8 ➡ **Profile Menu Options**.
Set **Barcode read for profile** to **true** in order to enable the Auto Profile Selection via QR Code function.
Set the **Barcode separator** if a character is used to separate data within the QR code. In this example, the data is separated by a comma. If a separator is not used, leave this field blank.



2. Set the location of the surface profile within the QR code in the **Barcode profile location** field.

In this example, the profile name begins in the first place of the QR code, so it has location of 1.


If a separator is not used, then the length of the surface profile name is entered in **Barcode profile length**. Since a separator is used in this example, this field is left at zero.

3. If a drop note is included in the QR code, set **Barcode autofill note** to **true**. If no drop note is included, set this parameter to **false**.

Set the location (and length if appropriate) of the drop note text in the **Barcode note location** and **Barcode note length** fields.

In this example, the drop note is in the second location, since a comma is used as a separator. The length is left at zero.

4. Touch **Ok** to save the settings.




Press below to change value

Barcode read for profile - true **Ok**

Barcode separator - ,

Barcode profile location - 1 ▼

Barcode profile length - 0 **Cancel**



Press below to change value

Barcode profile location - 1 **Ok**

Barcode profile length - 0 ▲

Barcode autofill note - true ▼

Barcode note location - 2 **Cancel**

10 Troubleshooting



If you have difficulties in the functioning of the Surface Analyst, consult this troubleshooting guide to help solve the problem.


This guide is separated into sections by problem type to help you find the information you need easily.

10.1 General Operation	62
10.2 Drop Dispensing	63
10.3 Drop Detections	65
10.4 Results	66



If you do not find your problem here or you continue to experience difficulties, contact Brighton Science at 513.469.1800.





10.1 General Operation

Problem	Cause	Solution
Loss of power	Battery is not fully engaged.	Press the both ends of the battery into the Surface Analyst to make sure it is fully engaged.
	Battery is discharged.	Charge the battery.
	AC adapter is not fully connected.	Check the connection of the AC adapter to the Surface Analyst. Check to make sure the AC adapter is plugged into a functioning outlet.
<p>Pump pressure error</p> 	The pumping system is malfunctioning.	<p>Do a hard reset.</p>  <p>If the problem persists, contact Brighton Science.</p>




Problem	Cause	Solution
Surface Analyst does not respond.	System needs re-setting.	Do a hard reset.  If the problem persists, contact Brighton Science.
Power is on, but Surface Analyst does not boot up	Micro USB cable is connected with a computer.	Disconnect the Surface Analyst from the computer and turn off the Surface Analyst before restarting.

10.2 Drop Dispensing

Problem	Cause	Solution
Intermittent drop dispensing or drop splattering	Cartridge is nearly empty or is dried out due to non-use.	Change the cartridge. If the problem persists, contact Brighton Science.
	Air is in the line.	Perform an extended purge. If necessary, perform a continuous purge next.
Excessive, large satellites (small droplets surrounding the main drop)   Small satellites usually do not affect contact angle results.	Air is in the line.	Perform an extended purge. If necessary, perform a continuous purge next.
	Valve period needs adjusting.	Contact Brighton Science for assistance.

Problem	Cause	Solution
<p>Air bubble in drop</p>  <p> Air bubbles usually only affect contact angle results for contact angles above 50 degrees.</p>	Air is in the line.	Perform an extended purge. If necessary, perform a continuous purge next.
<p>Vapor ring is present and is causing bad drop detections.</p>  <p>Vapor ring</p>	Drop settle time is too short.	Increase the drop settle time by .05 seconds.
<p>Fluid does not dispense, and there is a droplet that forms at the nozzle.</p> 	There is a failure of the equipment.	Perform a continuous purge. If the problem persists, contact Brighton Science.

10.3 Drop Detections

Problem	Cause	Solution
Drop detection does not match up with the drop outline 	The feet or base of the inspection head was not in firm contact with the surface during measurement.	Make sure to hold the inspection head squarely against the surface. Do not move the head during the measuring process.
	Auto Drop Center is disabled	Enable Auto Drop Center (ADC)
Drop detection is inside the edge of the droplet. 	If this happens regularly, the Near Pass Multiplier setting needs to be adjusted.	Increase the Near Pass Multiplier (3 Near)
Drop detection is outside the edge of the droplet. 	If this happens regularly, the Far Pass Multiplier setting needs to be adjusted.	Decrease the Far Pass Multiplier (3 Far).

10.4 Results

Problem	Cause	Solution
The Surface Analyst is not reporting the expected results. Contact angles are consistently too high or too low.	Over time, the Surface Analyst needs to be fine tuned for optimal performance.	Do a performance verification check with a new PCS card.



brighton-science.com